

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	131861 KM
File nr. :	1439289	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FJY504 / WWZZZ6RZEY037957 /		yr of constructionr :	/
E-File nr. :		First registration :	22/07/2013
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / POLO	Fuel type :	DIESEL
Object nr. :	713108	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	HANDSON & PARTNERS NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	POLO Trendline DPF 75PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1199
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	75	kW:	55
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	[x]
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	4-6/	Rim :		Hubcap :
Wheel RL :	[x]	DUNLOP	Tyre :	OK	4-6/	Rim :		Hubcap :
Wheel FR :	[x]	DUNLOP	Tyre :	OK	4-6/	Rim :		Hubcap :
Wheel RR :	[x]	DUNLOP	Tyre :	OK	4-6/	Rim :		Hubcap :
Wheel RES:	[x]		Tyre :	OK	>6/	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	175	75	R	14	T
Rear tyre	175	75	R	14	T

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :		Hubcap :
Wheel RL :			Tyre :	OK	/	Rim :		Hubcap :
Wheel FR :			Tyre :	OK	/	Rim :		Hubcap :
Wheel RR :			Tyre :	OK	/	Rim :		Hubcap :
Wheel RES:			Tyre :	OK	/	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	OTHER DAMAGES	POLIEREN
[x]	WINDSCREEN/CENTER/LEFT	CHIPS	HERST.CARGLASS
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	
[x]	BONNET/CENTER/RIGHT/FRONT	DENT	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR

1	2	3	4	5	6	7	8	9	10
169.44	0	0	0	0	0	0	0	0	0
84.72	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	169.44	0	169.44
HOG: 0	BG: 1		NA Deprec. 84.72
			0.00%
			TOTAL 84.72

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/09/2017 Hour : 14:50 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	