

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 38705 KM |
| File nr. : | 1436759 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FHW439 / YV1MV8481E2086419 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 03/07/2013 |
| VFS-nr. : | | Color : | BLUE D |
| Make + Model : | VOLVO / V40 | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | BELGACOM INS/FLEET NV | Co2: | 88g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | V40 D2 Base 115PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1560 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 114 | kW: | 84 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |
| General condition: | | | |

| | |
|--------------------------------|-----------------------------|
| Original registr. number : OK | Service manual : OK [x] |
| Cert. of reg. / Part 1: OK [x] | Cert. of conformity : OK |
| Cert. of reg. copy / Part 2: | Insurance certificate : |
| Warning vest : | Transport licence : |
| Tax certificate : | Navigation CD/SD/DVD OK [x] |
| Fuel card : | Car radio : OK [x] |
| Mobile phone kit : | Extinguisher : OK [x] |
| First aid kit : OK [x] | Warning triangle : OK [x] |
| Jack, wheelspanner : | Oil level : OK [x] |
| | Filled up : 0 |

Wheels and tyres: Summer tires

| |
|---|
| Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap : |
| Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RES: [x] ANDERE Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 55 | R | 16 | H |
| Rear tyre | 205 | 55 | R | 16 | H |

Remark : REP. KIT OK

Wheels and tyres:

| |
|---|
| Wheel FL: Tyre : OK / Rim : / Hubcap : |
| Wheel RL : Tyre : OK / Rim : / Hubcap : |
| Wheel FR : Tyre : OK / Rim : / Hubcap : |
| Wheel RR : Tyre : OK / Rim : / Hubcap : |
| Wheel RES: Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|--------------------------|--------------------------------|
| [x] | REAR DOOR/CENTER/LEFT | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | REAR BUMPER/RIGHT/CORNER | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | REAR MUDGUARD/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE |
| [x] | REAR DOOR/RIGHT/CENTER | DENT |
| [x] | WINDSCREEN/CENTER/RIGHT | CHIPS |

Interior

| | | |
|-----|-------------|-----------|
| [x] | BOOT LID IN | SCRATCHED |
|-----|-------------|-----------|

STATUS: NOT ACCEPTABLE

Accessories and others

| | | | | | |
|-----|------------------------------|-------------------|---------------|-------|-----------|
| [x] | OUTSIDE MIRROR LEFTHAND SIDE | BROKEN / CRACKED | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |

Others

RIM REAR RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 1 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|----------------|------------|-------|----------|
| 2 | 1 | SIDE INDICATOR | 6.00 EUR | 50 % | 6.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|-------|---|---|---|---|---|---|---|----|
| 95.00 | 30.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 95.00 | 15.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|-------------------|
| 95.00 | 30.00 | 0 | 125.00 |
| HOG: 0 | BG: 0 | | NA Deprec. 110.00 |
| | | | 0.00% |
| | | | TOTAL 110.00 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : NAVI OK [x] | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 13/09/2017 Hour : 15:35 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |