

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	142291 KM
File nr. :	1438381	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GCR409 / YV1DZ31A1E2572704 /		yr of constructionr :	/
E-File nr. :		First registration :	02/01/2014
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / XC60	Fuel type :	DIESEL
Object nr. :	62329	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SOLVAY CHEMICALS INTERNATIONAL	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	XC60 D3 Kinetic 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1984
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1: OK	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	GOODYEAR	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RL :	GOODYEAR	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel FR :	GOODYEAR	Tyre :	OK	2-4/	Rim :	WHEEL SCRATCHED	Hubcap :
Wheel RR :	GOODYEAR	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	235	65	R	17	H
Rear tyre	235	65	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR WINDOW/LEFT SCRATCH WITH PAINT DAMAGE
- [x] REAR MUDGUARD/RIGHT/FRONT DENT
- [x] REAR DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E
			Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR	50 %	211.80 EUR
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	INWERKING	
			Depr.	Total
2	0 LU =0.00 EUR	290.08 EUR	50 %	290.08 EUR

1	2	3	4	5	6	7	8	9	10
211.80	290.08	0	0	0	0	0	0	0	0
105.90	145.04	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	501.88	0	501.88
HOG: 0	BG: 0		NA Deprec. 250.94
			0.00%
			TOTAL 250.94

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/09/2017 Hour : 09:35 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	