

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	138777 KM
File nr. :	1438450	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CJZ045 / WV1ZZZ7HZCH054272 /		yr of constructionr :	/
E-File nr. :		First registration :	15/12/2011
VFS-nr. :		Color :	WHITE
Make + Model :	VOLKSWAGEN / TRANSPORTER	Fuel type :	DIESEL
Object nr. :	205	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Jungheinrich nv	Co2:	190g/km
Driver :		Remote controls:	2
Covering :	IMITATION LEATHER	Number keys :	3 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	TRANSP.1200 B/F SWB 84PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1968
Gear box :	Manueel	Number of places:	3
Number of gears:	5	Number of doors:	4
HP:	84	kW:	62
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	NOK [x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK [x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	65	R	16	R
Rear tyre	205	65	R	16	R

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:			Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/CENTER	DENT		
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE	HERSTELD	
[x]	FRONT THRESHOLD/RIGHT/REAR	OTHER DAMAGES	ROEST	
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE		
-----	-------------------------	---------------------------	--	--

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-kunst-01 PLASTICS REPAIR	110.64 EUR		110.64 EUR

Accessories and others

[x]	LOGO	MISSING/INCOMPLETE		
-----	------	--------------------	--	--

Number	Code	Description	Unit price	Depr.	Total
2	A 1	a-vab-verva-29 REPLACE	21.60 EUR	50 %	21.60 EUR

1	2	3	4	5	6	7	8	9	10
110.64	21.60	0	0	0	0	0	0	0	0
110.64	10.80	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
110.64	0	21.60	132.24
HOG: 0	BG: 3		NA Deprec. 121.44
			0.00%
			TOTAL 121.44

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/09/2017 Hour : 12:00 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	