

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: DIRTY [x] EXT: DIRTY [x] |
| Owner : | | Mileage : | 79361 KM |
| File nr. : | 1441274 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FPM597 / YV1MV848BE2100577 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 16/09/2013 |
| VFS-nr. : | | Color : | BLUE |
| Make + Model : | VOLVO / V40 | Fuel type : | DIESEL |
| Object nr. : | 701860 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | INTER IKEA HOLDING SERVICES SA | Co2: | 102g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | V40 D2 Base Powershift 115PK Aut. | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | |
| Variant car: | | Engine size: | 1560 |
| Gear box : | Automaat algemeen | Number of places: | 5 |
| Number of gears: | | Number of doors: | 5 |
| HP: | 114 | kW: | 84 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|----|-------------------------|-----------------------|-----|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | | |
| Fuel card : | | Car radio : | OK | [x] |
| Mobile phone kit : | | Extinguisher : | OK | [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK |
| Jack, wheelspanner : | | Oil level : | OK | [x] |
| | | Filled up : | 0 | |

Wheels and tyres: Summer tires

| | | | | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | | | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 55 | R | 16 | V |
| Rear tyre | 205 | 55 | R | 16 | V |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|---------------------------|--------------------------------|
| [x] | REAR BUMPER/CENTER/LEFT | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | REAR DOOR/RIGHT/FRONT | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT DOOR/LEFT/REAR | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT DOOR/LEFT/FRONT | DENT |
| [x] | FRONT DOOR/RIGHT/REAR | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT MUDGUARD/RIGHT/REAR | SCRATCH (WITHOUT PAINT DAMAGE) |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | |
|-----|---------------------------|---------------------------|----------------------|--------------|--------------|
| [x] | REAR MUDGUARD/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE | + DEUKEN | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 5 | 10 LU =48.00 EUR | 308.20 EUR | | 50 % | 356.20 EUR |
| [x] | REAR MUDGUARD/RIGHT/FRONT | DENT | | | |
| | Number Code | Description | Unit price | Depr. | Total |
| 6 | I 1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |
| [x] | REAR THRESHOLD/LEFT/REAR | SCRATCH WITH PAINT DAMAGE | | | |
| | Number Code | Description | Unit price | Depr. | Total |
| 2 | I 1 i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | | 115.56 EUR |
| [x] | REAR THRESHOLD/RIGHT/REAR | SCRATCH WITH PAINT DAMAGE | | | |
| | Number Code | Description | Unit price | Depr. | Total |
| 3 | I 1 i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | | 115.56 EUR |
| [x] | BONNET/CENTER/RIGHT/FRONT | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 4 | 0 LU =0.00 EUR | 290.08 EUR | | 50 % | 290.08 EUR |

Others

CLEANLINESS INTERIOR

| | Number | Code | Description | Unit price | Depr. | Total |
|---|--------|-----------------------------|-------------------|------------|-------|-----------|
| 1 | I 3 | personenwagen-a-vab-rein-02 | CLEANING INTERIOR | 11.47 EUR | | 34.41 EUR |

RIM FRONT LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 7 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM REAR LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 7 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM REAR RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 7 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 7 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|--------|--------|--------|--------|-------|--------|---|---|----|
| 34.41 | 115.56 | 115.56 | 290.08 | 356.20 | 63.00 | 380.00 | 0 | 0 | 0 |
| 34.41 | 115.56 | 115.56 | 145.04 | 178.10 | 63.00 | 380.00 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|----------------------|
| 708.53 | 646.28 | 0 | 1354.81 |
| HOG: 0 | BG: 0 | | NA Deprec. 1031.67 |
| | | | 0.00% |
| | | | TOTAL 1031.67 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 26/09/2017 Hour : 11:58 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |