

www.vabfleetservices.be Date: 24/08/2017 1/4

CD5ZS4

## [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	46150 KM
File nr. :	1431020	Mileage start / arrival:	0/0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HKL215 / WAUZZZ8V2FA0	018551 /	yr of constructionr :	/
E-File nr. :		First registration :	11/08/2014
VFS-nr. :		Color :	BLUE
Make + Model :	AUDI / A3 SPORTBACK	Fuel type :	DIESEL
Object nr. :	59676	Fuel:	
Classification:	Е	Environment Class:	EURO 6
Customer company :	VERIZON BELGIUM LUXEMBOURG NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

Variant car:		Engine size:	1598			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	5			
HP:	110	kW:	81			
Fisc HP		Imported vehicle:				
Animals transported:		Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:						

Metallic paint:

Yes



www.vabfleetservices.be Date: 24/08/2017 2/4

Original registr. number : OK Service manual : OK [x] Cert. of reg. / Part 1: OK [x] Cert. of conformity: OK Insurance certificate: Cert. of reg. copy / Part 2: Warning vest: Transport licence: Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK [x] Mobile phone kit : Extinguisher: Warning triangle: OK [x]

Oil level:

Filled up:

OK

0

[x]

#### Wheels and tyres: Summer tires

OK

[x]

Wheel FL:	[x]	CONTINENTAL	Tyre:		OK	[x]	4-6 /	Rim:	/ Hubcap:
Wheel RL:	[x]	CONTINENTAL	Tyre:		OK	[x]	4-6 /	Rim:	/ Hubcap:
Wheel FR:	[x]	CONTINENTAL	Tyre:	[x]	OK	[x]	4-6 /	Rim:	/ Hubcap:
Wheel RR:	[x]	CONTINENTAL	Tyre:		OK	[x]	4-6 /	Rim:	/ Hubcap:
Wheel RES:	[x]	CONTINENTAL	Tyre:		OK	[x]	>6 /	Rim:	/ Hubcap:

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	55	R	16	W
Rear tyre		205	55	R	16	W

Remark:

First aid kit :

Jack, wheelspanner :

#### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 24/08/2017 3/4

### STATUS: ACCEPTABLE / USAGE DAMAGE

#### **Bodywork \& windows**

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

[x] ROOF/CENTER/RIGHT OTHER DAMAGES

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 1		NA Deprec.	0
			0.00%	ı
			TOTAL	0



www.vabfleetservices.be Date: 24/08/2017 4/4

[x] = Status Modification

**Pictures:** No

rictures: No									
CIRCUMST	<b>TANCES</b>		NORMAL CONCLUSION						
Extra Time :	0 min	Waiting the Reason :	Waiting time: 0 min Reason:		Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No	<u> </u>							
Remark:									
Prices in EUR w	ithout VAT								
Authorized by customer :				Executed by VAB Fleet Se	ervices				
Remark authorized c	customer :								
Date :	24/08/2017	Hour:	09:34						
Company :									
Executed by VAB Flo Services	eet								
E-Mail :	@								
Signature authorized b	oy customer		<u>-</u>						