

www.vabfleetservices.be Date: 26/09/2017 1/4

CSH3XN

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	167328 KM
File nr. :	1442958	Mileage start / arrival:	0/0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FNT353 / WAUZZZ8U8DR	107126 /	yr of constructionr :	/
E-File nr. :		First registration :	02/09/2013
VFS-nr. :		Color :	SILVER
Make + Model :	AUDI / Q3	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	PURATOS NV	Co2:	137g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	Q3 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes				
Variant car:		Engine size:	1968				
Gear box :	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	5				
HP:	136	kW:	100				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:					
		Use:	Unknown				
General condition:							



Date: 26/09/2017 www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :			Transport licence :		
Γax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:		/ Hubcap:		
Wheel RL:	Tyre:	OK	/	Rim:		/ Hubcap:		
Wheel FR:	Tyre:	OK	/	Rim:		/ Hubcap:		
Wheel RR:	Tyre:	OK	/	Rim:		/ Hubcap:		
Wheel RES:	Tyre:	OK	/	Rim:		/ Hubcap:		
Width Height			Туре	Rim	Index			
Front tyre	0		0			0		

_		Width	Height	Туре	Rim	Index
	Front tyre	0	0		0	
	Rear tyre	0	0		0	
L	ical tyle	3	3		3	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Type	Rim	Index
Front tyre	0	0		0	
Rear tyre	0	0		0	

Remark:



www.vabfleetservices.be Date: 26/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE	Bodywork \& windows								
	H WITH PAINT DAMAGE	[x] REAR BUMPER/LEFT/LEFT	[x]						
[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE	H WITH PAINT DAMAGE	[x] REAR BUMPER/CENTER/RIGHT	[x]						
[x] WINDSCREEN/CENTER/LEFT WINDOW DAMAGE HERSTELD	V DAMAGE HERSTELD	[x] WINDSCREEN/CENTER/LEFT	[x]						

CHIPS

STATUS: NOT ACCEPTABLE

BONNET/CENTER/RIGHT/FRONT

Bodywork \& windows

[x]	FRONT/RIGHT		HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.	Total
	1 10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

Pieces

N	lumber	Code	Description	Unit price	Depr.	Total
1	1	FRONT		28.80 EUR	50 %	28.80 EUR

1	2	3	4	5	6	7	8	9	10
76.80	0	0	0	0	0	0	0	0	0
38.40	0	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
76.80		0	76.80	0
38.40	NA Deprec.		BG: 0	HOG: 0
	0.00%			
38.40	TOTAL			



www.vabfleetservices.be Date: 26/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	STANCES	NORMAL CONCLUSION				
Extra Time :	0 min	Waiting time: 0 min Reason:		Towing time : Reason :	0 min	
NOT EXECUTED Reason:	D: No			<u> </u>		
Remark :						
Prices in EUR	without VAT					
Authorized by customer :			Executed by VAB Fleet	Services		
Remark authorize	ed customer :					
Date :	26/09/2017	Hour: 09:43				
Company : Executed by VAB Services	Fleet					
E-Mail :	@					
Signature authorize	ed by customer					