

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	107269 KM
File nr. :	1433518	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
KAPAZABE / WBA3Y11050D376189 /		yr of constructionr :	/
E-File nr. :		First registration :	21/05/2015
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 3 GT	Fuel type :	DIESEL
Object nr. :	61157	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KAPAZA BELGIUM NV	Co2:	127g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	143	kW:	105
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK [x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK [x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x] OK [x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK [x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	18	H
Rear tyre	225	50	R	18	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE
- [x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
7	0 LU =0.00 EUR		254.16 EUR		50 %
					254.16 EUR
[x]	REAR MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
6	0 LU =0.00 EUR		369.84 EUR		50 %
					369.84 EUR
[x]	REAR MUDGUARD/RIGHT/REAR	DENT			
	Number	Code	Description	Unit price	Depr.
	Total				
0	0				
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
8	0 LU =0.00 EUR		369.84 EUR		50 %
					369.84 EUR
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			+DEUK
			Repair paint - LI	New paint - E	Depr.
					Total
9	0 LU =0.00 EUR		382.02 EUR		50 %
					382.02 EUR
[x]	WINDSCREEN/CENTER/RIGHT	HOLE/CRACK/TORN			2X
			Repair paint - LI	New paint - E	Depr.
					Total
10	0 LU =0.00 EUR		0 EUR		50 %
			Repair paint - LI	New paint - E	Depr.
					Total
10	25 LU =120.00 EUR		0 EUR		50 %
					120.00 EUR
[x]	FRONT MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			+DEUK
			Repair paint - LI	New paint - E	Depr.
					Total
5	0 LU =0.00 EUR		264.21 EUR		50 %
					264.21 EUR

[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	ISOLATIE BINNENIN		
		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
10	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR	264.21 EUR		50 %	264.21 EUR
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE			
	Number Code	Description	Unit price	Depr.	Total
0	0				
[x]	LIGHTS/LEFT/FRONT	HOLE/CRACK/TORN	DAGLICHT		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
4	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	FRONT BUMPER/RIGHT	OTHER DAMAGES	ADEKKING TREKOOG		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	0 EUR		50 %	
[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	FIXATION COVER	36.00 EUR	50 %	36.00 EUR

Number	Code	Description	Unit price	Depr.	Total
4	1	DAGLICHT	50.00 EUR	50 %	50.00 EUR

Number	Code	Description	Unit price	Depr.	Total
10	1	WIND SCREEN	440.64 EUR	50 %	440.64 EUR

Number	Code	Description	Unit price	Depr.	Total
10	1	ISOLATIE	50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
380.00	254.16	36.00	74.00	264.21	369.84	254.16	369.84	382.02	898.85
380.00	127.08	18.00	37.00	132.10	184.92	127.08	184.92	191.01	449.42

INNOVATIVE	TRADITIONAL	GENERAL	
380.00	2903.08	0	3283.08
HOG: 0	BG: 2		NA Deprec. 1831.54
			0.00%
			TOTAL 1831.54

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 04/09/2017 Hour : 07:47 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	