

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 120541 KM |
| File nr. : | 1438455 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1DPR077 / ZFA25000002164466 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 17/07/2012 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | FIAT / DUCATO | Fuel type : | DIESEL |
| Object nr. : | 47769 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | STABILAME SA | Co2: | 203g/km |
| Driver : | | Remote controls: | 1 |
| Covering : | IMITATION LEATHER | Number keys : | 1 [x] |
| Vehicle kind : | TRUCK, LORRY | Seats (minivan) : | 0 |
| Vehicle type : | DUCATO 35 CH1C LWB DPF(EU5) 177PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BESTELWAGEN | Engine size: | 2999 |
| Gear box : | Manueel | Number of places: | 3 |
| Number of gears: | 6 | Number of doors: | 3 |
| HP: | 177 | kW: | 130 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |
| General condition: | | | |

| | |
|-------------------------------------|---------------------------|
| Original registr. number : OK | Service manual : OK [x] |
| Cert. of reg. / Part 1: | Cert. of conformity : OK |
| Cert. of reg. copy / Part 2: OK [x] | Insurance certificate : |
| Warning vest : | Transport licence : |
| Tax certificate : | Navigation CD/SD/DVD |
| Fuel card : | Car radio : OK [x] |
| Mobile phone kit : | Extinguisher : OK [x] |
| First aid kit : OK [x] | Warning triangle : OK [x] |
| Jack, wheelspanner : | Oil level : OK [x] |
| | Filled up : 0 |

Wheels and tyres: Summer tires

| |
|---|
| Wheel FL: [x] UNIROYAL Tyre : OK [x] 2-4/ Rim : / Hubcap : |
| Wheel RL : [x] UNIROYAL Tyre : OK [x] 2-4/ Rim : / Hubcap : |
| Wheel FR : [x] UNIROYAL Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : |
| Wheel RR : [x] UNIROYAL Tyre : OK [x] 2-4/ Rim : / Hubcap : |
| Wheel RES: [x] UNIROYAL Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 215 | 70 | R | 15 | H |
| Rear tyre | 215 | 70 | R | 15 | H |

Remark :

Wheels and tyres:

| |
|---|
| Wheel FL: Tyre : OK / Rim : / Hubcap : |
| Wheel RL : Tyre : OK / Rim : / Hubcap : |
| Wheel FR : Tyre : OK / Rim : / Hubcap : |
| Wheel RR : Tyre : OK / Rim : / Hubcap : |
| Wheel RES: Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT DOOR/LEFT/Front SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR LIGHT/LEFT/CORNER WINDOW DAMAGE

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 6 0 LU =0.00 EUR | 0 EUR | | 50 % | |

[x] REAR LIGHT/RIGHT/CORNER HOLE/CRACK/TORN

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 6 0 LU =0.00 EUR | 0 EUR | | 50 % | |

[x] REAR DOOR/RIGHT/CENTER DENT

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 5 0 LU =0.00 EUR | 0 EUR | | 50 % | |

| | Repair paint - LI | New paint - E | Depr. | Total |
|---------------------|-------------------|---------------|-------|------------|
| 5 30 LU =144.00 EUR | 0 EUR | | 50 % | 144.00 EUR |

[x] THRESHOLD FRONT/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|------------|
| 2 0 LU =0.00 EUR | 232.88 EUR | | 50 % | 232.88 EUR |

[x] WINDSCREEN/CENTER/LEFT WINDOW DAMAGE

| | Repair paint - LI | New paint - E | Depr. | Total |
|---------------------|-------------------|---------------|-------|------------|
| 8 25 LU =120.00 EUR | 0 EUR | | 50 % | 120.00 EUR |

[x] FRONT THRESHOLD/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|------------|
| 1 0 LU =0.00 EUR | 232.88 EUR | | 50 % | 232.88 EUR |

[x] FRONT BUMPER/LEFT/SIDE SCRATCH WITH PAINT DAMAGE

| Number | Code | Description | Unit price | Depr. | Total |
|--------|--------------------|-----------------|------------|-------|------------|
| 4 | I 1 i-vab-kunst-01 | PLASTICS REPAIR | 110.64 EUR | | 110.64 EUR |

[x] REAR DOOR/LEFT/LEFT DENT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-------------------|---------------|------------|-------|-----------|
| 3 | I 1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |

Accessories and others

[x] SIDE PROTECTION

MISSING/INCOMPLETE

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 7 0 LU =0.00 EUR | 0 EUR | | 50 % | |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-----------------|------------|-------|------------|
| 5 | 1 | DOOR REAR RIGHT | 275.40 EUR | 50 % | 275.40 EUR |
| Number | Code | Description | Unit price | Depr. | Total |
| 6 | 1 | REAR LIGHT | 67.50 EUR | 50 % | 67.50 EUR |
| Number | Code | Description | Unit price | Depr. | Total |
| 6 | 1 | REAR LIGHT | 67.50 EUR | 50 % | 67.50 EUR |
| Number | Code | Description | Unit price | Depr. | Total |
| 7 | 1 | SIDE PROTECTION | 10.80 EUR | 50 % | 10.80 EUR |
| Number | Code | Description | Unit price | Depr. | Total |
| 8 | 1 | WIND SCREEN | 275.40 EUR | 50 % | 275.40 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|-------|--------|--------|--------|-------|--------|---|----|
| 232.88 | 232.88 | 63.00 | 110.64 | 419.40 | 135.00 | 10.80 | 395.40 | 0 | 0 |
| 116.44 | 116.44 | 63.00 | 110.64 | 209.70 | 67.50 | 5.40 | 197.70 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 173.64 | 1426.36 | 0 | 1600.00 |
| HOG: 0 | BG: 3 | | NA Deprec. 886.82 |
| | | | 0.00% |
| | | | TOTAL 886.82 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 25/09/2017 Hour : 09:54 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |