

CQW73N

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	133016 KM
File nr. :	1441745	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DUR343 / WDF63960113759851 /		yr of constructionr :	/
E-File nr. :		First registration :	03/09/2012
VFS-nr. :		Color :	RED
Make + Model :	MERCEDES / VITO	Fuel type :	DIESEL
Object nr. :	12314	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MIELE NV 421000/800	Co2:	206g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	VITO 110 B/F SWB 95PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	2143
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	4
HP:	95	kW:	70
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	[x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	16	
Rear tyre	195	65	R	16	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		+DEUK	
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR DOOR/CENTER/RIGHT		DENT			
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		226.26 EUR		50 %	226.26 EUR
[x]	ROOF/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE		+DEUKEN	
			Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR		361.13 EUR		50 %	361.13 EUR
[x]	BONNET/CENTER/LEFT		OTHER DAMAGES		SLECHTE HERSTELLING	
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	REAR DOOR/LEFT/LEFT		OTHER DAMAGES		SLECHTE HERSTELLING	
	Number	Code	Description	Unit price	Depr.	Total
0	0					

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	45.88 EUR

1	2	3	4	5	6	7	8	9	10
45.88	110.64	226.26	361.13	0	0	0	0	0	0
45.88	110.64	113.13	180.56	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
156.52	587.39	0	743.91
HOG: 0	BG: 3		NA Deprec. 450.22
			0.00%
			TOTAL 450.22

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 27/09/2017 Hour : 14:00 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	