

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|--|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 171528 KM |
| File nr. : | 1441662 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FJR201 / W0LPD8EW5D8069030 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 18/07/2013 |
| VFS-nr. : | | Color : | BROWN D |
| Make + Model : | OPEL / ASTRA BREAK | Fuel type : | DIESEL |
| Object nr. : | 74324 | Fuel : | |
| Classification : | O | Environment Class: | EURO 5 |
| Customer company : | DELI NV | Co2: | 105g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | ASTRA BRE ecoFL.Enjoy Active St/St 110PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1686 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 110 | kW: | 81 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | OK [x] |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | OK | [x] | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | | | |
|------------|-----|-------------|--------|-----|-----|------|-------|-------|----------|----------|-----------|-----------|
| Wheel FL: | [x] | CONTINENTAL | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | [x] | SCRATCHED | |
| Wheel RL : | [x] | CONTINENTAL | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | [x] | SCRATCHED | |
| Wheel FR : | [x] | CONTINENTAL | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | / | Hubcap : | [x] | SCRATCHED |
| Wheel RR : | [x] | CONTINENTAL | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | [x] | SCRATCHED | |
| Wheel RES: | [x] | CONTINENTAL | Tyre : | OK | | / | Rim : | / | Hubcap : | | | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 50 | R | 17 | W |
| Rear tyre | 225 | 50 | R | 17 | W |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|--|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|-----------------------------|--------------------------------|
| [x] | REAR BUMPER/CENTER/RIGHT | SCRATCH WITH PAINT DAMAGE |
| [x] | REAR DOOR/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE |
| [x] | REAR DOOR/RIGHT/FRONT | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT MUDGUARD/RIGHT/CENTER | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | FRONT BUMPER/CENTER/RIGHT | SCRATCH WITH PAINT DAMAGE |

Interior

| | | |
|-----|------------|---------------|
| [x] | DOOR IN FL | OTHER DAMAGES |
|-----|------------|---------------|

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | |
|-----|--------------------------|---------------------------|----------------------|--------------|--------------|
| [x] | REAR DOOR/CENTER/RIGHT | DENT | +LAKSCHADE | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 4 | 0 LU =0.00 EUR | 301.68 EUR | | 50 % | 301.68 EUR |
| [x] | REAR MUDGUARD/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | 0 LU =0.00 EUR | 308.20 EUR | | 50 % | 308.20 EUR |
| [x] | REAR MUDGUARD/RIGHT/REAR | DENT | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 5 | 0 LU =0.00 EUR | 308.20 EUR | | 50 % | 308.20 EUR |
| [x] | REAR DOOR/LEFT/REAR | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | 0 LU =0.00 EUR | 318.35 EUR | | 50 % | 318.35 EUR |
| [x] | ROOF/CENTER/LEFT | OTHER DAMAGES | CHEMISCHE INWERKING | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 8 | 0 LU =0.00 EUR | 481.50 EUR | | 50 % | 481.50 EUR |
| [x] | FRONT DOOR/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | 318.35 EUR | | 50 % | 318.35 EUR |

[x] ROOF STYLE/FRONT/LEFT/CENTER DENT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-------------------|---------------|------------|-------|-----------|
| 9 | I 1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |

[x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|------------|
| 6 0 LU =0.00 EUR | 318.35 EUR | | 50 % | 318.35 EUR |

[x] BONNET/RIGHT/CENTER OTHER DAMAGES CHEMISCHE INWERKING

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|------------|
| 1 0 LU =0.00 EUR | 290.08 EUR | | 50 % | 290.08 EUR |

Others

HUB CAP FR

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 7 0 LU =0.00 EUR | | | 50 % | |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 7 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|--------|--------|-------|--------|-------|----|
| 290.08 | 318.35 | 626.55 | 301.68 | 308.20 | 318.35 | 30.00 | 481.50 | 63.00 | 0 |
| 145.04 | 159.18 | 313.28 | 150.84 | 154.10 | 159.18 | 15.00 | 240.75 | 63.00 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|--------------------|
| 63.00 | 2674.71 | 0 | 2737.71 |
| HOG: 0 | BG: 0 | | NA Deprec. 1400.36 |
| | | | 0.00% |
| | | | TOTAL 1400.36 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 27/09/2017 Hour : 16:25 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |