

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	186658 KM
File nr. :	1441212	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HKV743 / JMZGJ691651179283 /		yr of constructionr :	/
E-File nr. :		First registration :	13/08/2014
VFS-nr. :		Color :	BLACK
Make + Model :	MAZDA / 6 BREAK	Fuel type :	DIESEL
Object nr. :	12132	Fuel :	
Classification :	F	Environment Class:	EURO 6
Customer company :	WURTH BELUX NV	Co2:	110g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	2191
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	NOK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	[x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :		/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	17	W
Rear tyre	205	55	R	17	W

Remark : REPAIRKIT OK

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	REAR MUDGUARD/LEFT/FRONT	DENT
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	BONNET/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	-------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT DOOR/LEFT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT DOOR/RIGHT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x]	FRONT MUDGUARD/LEFT/REAR		DENT		MET LAKSCHADE				
			Repair paint - LI	New paint - E	Depr.			Total	
1	0 LU =0.00 EUR		220.18 EUR		50 %			220.18 EUR	
[x]	WINDSCREEN/BELOW/LEFT			OTHER DAMAGES		AFDEKKING			
			Repair paint - LI	New paint - E	Depr.			Total	
9	5 LU =24.00 EUR		0 EUR		50 %			24.00 EUR	
[x]	FRONT BUMPER/RIGHT			DENT		MET LAKSCHADE			
			Repair paint - LI	New paint - E	Depr.			Total	
5	0 LU =0.00 EUR		211.80 EUR					211.80 EUR	
	Number	Code	Description		Unit price	Depr.		Total	
5	I 1	i-vab-kunst-01	PLASTICS REPAIR		110.64 EUR			110.64 EUR	
[x]	WIND SCREEN/BELOW/RIGHT			OTHER DAMAGES		AFDEKKING			
			Repair paint - LI	New paint - E	Depr.			Total	
9	5 LU =24.00 EUR		0 EUR		50 %			24.00 EUR	

Interior

[x]	FLOOR FL			HOLE					
			Repair paint - LI	New paint - E	Depr.			Total	
8	40 LU =192.00 EUR		0 EUR		50 %			192.00 EUR	

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
8	1	CARPET	60.00 EUR	50 %	60.00 EUR
9	1	AFDEKKING	25.00 EUR	50 %	25.00 EUR
9	1	AFDEKKING	25.00 EUR	50 %	25.00 EUR

1	2	3	4	5	6	7	8	9	10
220.18	318.35	318.35	211.80	322.44	318.35	95.00	252.00	98.00	0
110.09	159.18	159.18	105.90	322.44	159.18	95.00	126.00	49.00	0

INNOVATIVE	TRADITIONAL	GENERAL	
205.64	1948.83	0	2154.47
HOG: 0	BG: 0		NA Deprec. 1285.96
			0.00%
			TOTAL 1285.96

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

<p>Authorized by customer : I KNOW THE STATE OF THE VEHICLE AND I AGREE WITH THE REPORT AND ITS ATTACHMENTS;</p> <p>Remark authorized customer :</p> <p>Date : 20/09/2017 Hour : 14:35</p> <p>Company :</p> <p>Executed by VAB Fleet Services</p> <p>E-Mail : @</p>	<p>Executed by VAB Fleet Services</p>
<p>Signature authorized by customer</p> 	