

www.vabfleetservices.be Date: 07/08/2017 1/5

C85LWK

X] EFFECTIVE [] NOT EXECUTED	[] COLLECTION	[] DELIVERY
-------------------------------	----------------	--------------

[x] = Status Modification

VAT over the margin - car:

No

Cleanliness: Commissionar: **KBC REMARKETING** INT: DIRTY [x] EXT: CLEAN [x] Owner: Mileage: 156947 KM File nr. : Mileage start / arrival: 1427212 0 / 0Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1ECZ826 / VF30A9HR8CS231978 / E-File nr. : First registration: 24/10/2012 VFS-nr.: Color: **BLACK** Make + Model : Fuel type : PEUGEOT / 5008 **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: **KBC BANK NV** 114g/km Driver : Remote controls: TISSUE Covering: Number keys: 1 [x] Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type : 5008 e-HDi Allure STT FAP BMP 112PK Aut. Country registration: **BELGIUM**

Variant car:		Engine size:	1560
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
нр:	112	kW:	82
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Metallic paint:



www.vabfleetservices.be Date: 07/08/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:		[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	FULDA	Tyre:	OK	[x] 2-4/	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel RL:	[x]	FULDA	Tyre:	OK	[x] 2-4/	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel FR:	[x]	FULDA	Tyre: [x]	OK	[x] 2-4/	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel RR:	[x]	FULDA	Tyre:	OK	[x] 2-4/	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel RES:	[x]		Tyre:	OK	[x] > 6/	Rim:			/ Hubcap:
			****		** * * * * * * * * * * * * * * * * * * *	-		T	Di 1 1

[x]	Width	Height	Туре	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 07/08/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

ST	ATUS: ACCEPTABLE /	USAGE DAMA	GE			
Во	dywork \& windows					
[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAI	NT DAMAGE		
[x]	REAR DOOR/CENTER/LEFT		DENT			
[x]	REAR MUDGUARD/LEFT/FRONT		SCRATCH (WITHOUT	Γ PAINT DAMAGE)	
[x]	ROOF/REAR/LEFT		DENT			
[x]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAI	NT DAMAGE		
[x]	FRONT DOOR/RIGHT/FRONT		SCRATCH WITH PAI	NT DAMAGE		
[x]	BONNET/CENTER/LEFT/FRONT		CHIPS			
Inte	erior					
[x]	CENTER CONSOLE		CARVED			
[x]	BOOT LID IN		CARVED			
ST	ATUS: NOT ACCEPTAB	BLE				
Во	dywork \& windows					
[x]	REAR MUDGUARD/RIGHT/FRONT		DENT			
	Number Code	Description		Unit price	Depr.	Total
	3 I 1 i-vab-uitd-01	BEAT OUT DENT		63.00 EUR		63.00 EUR
[x]	WINDSCREEN/CENTER/RIGHT		WINDOW DAMAGE			

[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE

Description

WINDOW REPAIR

Repair paint - LI

2 0 LU =0.00 EUR	211.80 EUR	50 %	211.80 EUR

New paint - E

Unit price

58.80 EUR

Depr.

Depr.

Total

58.80 EUR

Total

Interior

Number Code

i-vab-herstr-01

I 1

[x]	FLOOR FL	HOLE

	Number	Code	Description	Unit price	Depr.	Total	
1	I 1	i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR		43.92 EUR	



www.vabfleetservices.be Date: 07/08/2017 4/5

CLEANLI	INESS INTERIOR	₹							
Number	Code		Description	ı		Unit price	e Depr.		Total
1 I 2	personenwagen-a	-vab-rein-02	CLEANING	INTERIOR		11.47 EUI	₹		22.94 EU
RIM FRO	NT LEFT								
Number	Code		Description	ı		Unit price	e Depr.		Total
5 I 1	i-vab-herstalu-02		REPAIR AI	LOY WHEEL		95.00 EUI	2		95.00 E
RIM REA	R RIGHT								
Number	Code		Description	ı		Unit price	e Depr.		Total
5 I 1	i-vab-herstalu-02		REPAIR AI	LOY WHEEL		95.00 EUI	2		95.00 E
RIM FRO	NT RIGHT								
Number			Description	ı		Unit price	e Depr.		Total
5 I 1 i-vab-herstalu-02			REPAIR AI	LLOY WHEEL		95.00 EUI	R		95.00 E
1	2	3	4	5	6	7	8	9	10
66.86	211.80	63.00	58.80	285.00	0	0	0	0	0
(()(105.90	63.00	58.80	285.00	0	0	0	0	0
66.86		TRAD	TIONAL	GE	NERAL				
INNOV	ATIVE			0		6			
INNOV	ATIVE 3.66		1.80		0				6
INNOV 473		21	1.80 G: 0		0	NA Depre	ec.		68



www.vabfleetservices.be Date: 07/08/2017 5/5

[x] = Status Modification

Pictures: No

netures.							
CIRCUMS	TANCES		NORMAL CONCLUSION				
Extra Time :	0 min	Waiting time: 0 mi	in	Towing time : Reason :	0 min		
NOT EXECUTED : No Reason :				l			
Remark:							
Prices in EUR v	without VAT						
Authorized by customer :			Executed by VAB Fleet So	ervices			
Remark authorized	customer :						
Date :	07/08/2017	Hour: 11:43					
Company :							
Executed by VAB F Services	Fleet						
E-Mail :	@						
Signature authorized	by customer						