

www.vabfleetservices.be Date: 27/09/2017 1/5

CRB4GA

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: DIRTY [x] EXT: DIRTY [x] Owner: Mileage : 119174 KM File nr. : Mileage start / arrival: 0 / 01442046 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FPA641 / TMBJG9NE2E0048941 / E-File nr. : First registration: 11/09/2013 Color: VFS-nr.: **BLACK** Make + Model : Fuel type : SKODA / OCTAVIA COMBI **DIESEL** Object nr. : Fuel: 44538 Classification: **Environment Class:** EURO 5 Customer company: Co2: DLV Belgium cvba 99g/kmDriver : Remote controls: 2 PARTIAL LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: OCTAVIA COMBI Elegance 105PK Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes	
Variant car:	BREAK	Engine size:	1598	
Gear box :	Manueel	Number of places:	5	
Number of gears:	5	Number of doors:	5	
HP:	105	kW:	77	
Fisc HP		Imported vehicle:		
Animals transported:	No	Smoked in vehicle:	No	
Due date vehicle inspection:		Extra set of tires:	No	
		Use:	Unknown	
General condition:		1		



www.vabfleetservices.be Date: 27/09/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:			
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:			
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:			
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:			
Wheel RES:	[x]	MICHELIN	Tyre:		OK		/	Rim:			/ Hubcap:			
														_

[x]	Width	Height	Туре	Rim	Index
Front tyre	225	45	R	17	W
Rear tyre	225	45	R	17	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

[x	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



Date: 27/09/2017 www.vabfleetservices.be 3/5

REAR DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE REAR DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE REAR DOOR/LEFT/FRONT SCRATCH WITH PAINT DAMAGE REAR DOOR/LEFT/FRONT SCRATCH WITHOUT PAINT DAMAGE REAR DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE REAR DOOR/RIGHT/CENTER DENT REAR DOOR/RIGHT/CENTER DENT STATUS: NOT ACCEPTABLE Bodywork \& windows REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE REAR DOOR/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE REAR DOOR/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE REAR DOOR/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE REAR MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE REAR MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE Repair paint - LI New paint - E Depr. Total 2 OLU = 0.00 EUR 308.20 EUR 50 % 308.20 EUR INTERIOR SCRATCH WITH PAINT DAMAGE Repair paint - LI New paint - E Depr. Total 1 OLU = 0.00 EUR 308.20 EUR 50 % 308.20 EUR INTERIOR SCRATCH WITH PAINT DAMAGE Repair paint - LI New paint - E Depr. Total 1 OLU = 0.00 EUR 308.20 EUR 50 % 308.20 EUR INTERIOR SCRATCH WITH PAINT DAMAGE SCRATCH WITH PAINT DAMAGE REPAIR MUDGUARD/LEFT/CENTER	ST	ATUS: ACCEPTABLE /	USAGE DAMA	GE		
REAR DOOR/LEFT/FRONT SCRATCH WITH PAINT DAMAGE REAR DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE) FRONT DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE) FRONT MUDGUARD/RIGHT/CENTER DENT FRONT MUDGUARD/RIGHT/CENTER DENT STATUS: NOT ACCEPTABLE Bodywork \& windows REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE REAR DOOR/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE REAR DOOR/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE REAR DOOR/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE REAR MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE REAR DOOR/LEFT	Во	dywork \& windows				
REAR DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)	[x]	REAR DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAM	IAGE	
FRONT DOORRIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE) FRONT MUDGUARD/RIGHT/CENTER DENT STATUS: NOT ACCEPTABLE Bodywork \& windows	[x]	REAR DOOR/LEFT/FRONT		SCRATCH WITH PAINT DAM	IAGE	
STATUS: NOT ACCEPTABLE	[x]	REAR DOOR/RIGHT/CENTER		SCRATCH (WITHOUT PAINT	DAMAGE)	
STATUS: NOT ACCEPTABLE Bodywork \& windows	[x]	FRONT DOOR/RIGHT/CENTER		SCRATCH (WITHOUT PAINT	DAMAGE)	
REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE	[x]	FRONT MUDGUARD/RIGHT/CENTER		DENT		
REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE	ST	ATUS: NOT ACCEPTAE	BLE			
Repair paint - LI New paint - E Depr. Total 3 0 LU = 0.00 EUR	Во	dywork \& windows				
REAR DOOR/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE	[x]	REAR BUMPER/RIGHT/RIGHT		SCRATCH WITH PAINT DAM	IAGE	
REAR DOOR/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE Repair paint - LI New paint - E Depr. Total			Repair paint - LI	New paint - E	Depr.	Total
Repair paint - LI		3 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
S O LU = 0.00 EUR 301.68 EUR 50 % 301.68 EUR	[x]	REAR DOOR/CENTER/RIGHT		SCRATCH WITH PAINT DAM	1AGE	
REAR MUDGUARD/LEFT/CENTER Repair paint - LI New paint - E Depr. Total 10 LU = 0.00 EUR 308.20 EUR Interior [x] SEAT FR Repair paint - LI New paint - E Depr. Total Depr. Total			Repair paint - LI	New paint - E	Depr.	Total
Repair paint - LI New paint - E Depr. Total 2 0 LU = 0.00 EUR 308.20 EUR 50 % 308.20 EUR Interior [x] SEAT FR HOLE Repair paint - LI New paint - E Depr. Total		5 0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR
2 0 LU = 0.00 EUR 308.20 EUR 50 % 308.20 EUR Interior [x] SEAT FR HOLE Repair paint - LI New paint - E Depr. Total	[x]	REAR MUDGUARD/LEFT/CENTER		SCRATCH WITH PAINT DAM	IAGE	
Interior [x] SEAT FR HOLE Repair paint - LI New paint - E Depr. Total			Repair paint - LI	New paint - E	Depr.	Total
[x] SEAT FR HOLE Repair paint - LI New paint - E Depr. Total		2 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
Repair paint - LI New paint - E Depr. Total	Inte	erior				
	[x]	SEAT FR		HOLE		
1 25 LU =120.00 EUR 0 EUR 50 % 120.00 EUR			Repair paint - LI	New paint - E	Depr.	Total
		1 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

	CLEANL	INESS INTERIOR				
	Number	Code	Description	Unit price	Depr.	Total
1	Ι3	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		43.74 EUR
	RIM FRO					
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	_	95.00 EUR



www.vabfleetservices.be Date: 27/09/2017 4/5

Number	Code		Description			Unit pric	ce Depr.		Total
1 1	ZETELBEKLED	DING				120.00 E	50 %		120.00 EUR
1	2	3	4	5	6	7	8	9	10
283.74	308.20	211.80	95.00	301.68	0	0	0	0	0
163.74	154.10	105.90	95.00	150.84	0	0	0	0	0
INNOV	ATIVE	TRADI	TIONAL	GI	ENERAL				
138	3.74	100	51.68		0				1200.
НО	G: 0	В	G: 0			NA Depr	rec.		66
						0.00%			

TOTAL

669.58



www.vabfleetservices.be Date: 27/09/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMST	TANCES		UNDER CONDITION - DUSTY VEHICLE					
Extra Time :	0 min	Waiting time: 0 m Reason:	nin	Towing time : Reason :	0 min			
NOT EXECUTED:	No	_						
Reason :								
Remark:								
Prices in EUR wi	ithout VAT							
Authorized by customer:			Executed by VAB Fleet	Services				
Remark authorized c	ustomer :							
Date :	27/09/2017	Hour: 13:22						
Company :								
Executed by VAB Fle Services	eet							
E-Mail :	@							
Signature authorized b	y customer							