

www.vabfleetservices.be Date: 25/09/2017 1/4

CQ9UTP

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

109gr.105PK

No

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 163480 KM File nr. : Mileage start / arrival: 1441232 0 / 0Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1CNA926 / TMBHT21Z4C2105474 / E-File nr. : First registration: 09/01/2012 VFS-nr.: Color: **BLACK** Make + Model : Fuel type : SKODA / OCTAVIA BREAK **DIESEL** Object nr. : Fuel: 5001 **Environment Class:** Classification: EURO 5 Customer company: Co2: INBEV BELGIUM SA 109g/km Driver : Remote controls: TISSUE Covering: Number keys : 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 OCTAVIA COMBI Ambiente DPF Vehicle type: Country registration: **BELGIUM**

		_	
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	

Metallic paint:

Yes



www.vabfleetservices.be Date: 25/09/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

	[x] Width Height			Type		Rim	Index						
Wheel RES:	[x]		Tyre:	OI	ζ.	/	Rim:				/ Hubcap:		
Wheel RR:	[x]	GOODYEAR	Tyre:	OI	ζ	[x] 2-4/	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		
Wheel FR:	[x]	GOODYEAR	Tyre: [[x] OI	ζ	[x] 2-4/	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:		
Wheel RL:	[x]	GOODYEAR	Tyre:	OI	ζ	[x] 2-4/	Rim:	[x]	WHEEL SCRATCHEL)	/ Hubcap:		
Wheel FL:	[x]	GOODYEAR	Tyre:	OI	ζ	[x] 2-4/	Rim:	[x]	WHEEL SCRATCHEE)	/ Hubcap:		\Box

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	Н
Rear tyre	195	65	R	15	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 25/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/LEFT/REAR DENT

[x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

 Repair paint - LI
 New paint - E
 Depr.
 Total

 2 0 LU = 0.00 EUR
 211.80 EUR
 50 %
 211.80 EUR

[x] REAR MUDGUARD/LEFT/CENTER DENT

N	lumber	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	211.80	0	0	0	0	0	0	0	0
63.00	105.90	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
274.80	0	211.80	63.00
NA Deprec. 168.90		BG: 0	HOG: 0
0.000/			

0.00%
TOTAL 168.90



www.vabfleetservices.be Date: 25/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES		UNDER CONDITION - DUSTY VEHICLE					
Extra Time :	0 min	Waiting time: 0 r Reason:	nin	Towing time : Reason :	0 min			
NOT EXECUTED :	: No							
Remark :	1							
Prices in EUR v	vithout VAT							
Authorized by customer :			Executed by VAI	3 Fleet Services				
Remark authorized	customer :							
Date :	25/09/2017	Hour: 14:23						
Company : Executed by VAB F Services	leet							
E-Mail:	@							
Signature authorized	by customer							