

[X] EFFECTIVE [] NOT EXECUTED

[X] COLLECTION

[] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	112397 KM
File nr. :	1440427	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :	1GMK942 / TMBAE73T9E9046370 /	Mileag ref. service :	0
E-File nr. :		yr of constructionr :	/
VFS-nr. :		First registration :	11/03/2014
Make + Model :	SKODA / SUPERB	Color :	BLACK
Object nr. :	31852	Fuel type :	DIESEL
Classification :		Fuel :	
Customer company :	IMI HYDRONIC ENGINEERING NV	Environment Class:	EURO 5
Driver :		Co2:	119g/km
Covering :	LEATHER	Remote controls:	1
Vehicle kind :	VEHICLE	Number keys :	2 [x]
Vehicle type :		Seats (minivan) :	0
		Country registration :	BELGIUM

VAT over the margin - car:	Metallic paint:	Yes
Variant car:	Engine size:	1968
Gear box :	Number of places:	5
Number of gears:	Number of doors:	4
HP:	kW:	103
Fisc HP	Imported vehicle:	
Animals transported:	Smoked in vehicle:	No
Due date vehicle inspection:	Extra set of tires:	
	Use:	Unknown
General condition:		

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	Warning triangle :	OK	[x]
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :		0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :			/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	45	R	17	H
Rear tyre	225	45	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

Interior

[x] SEAT FL SCRATCHED

STATUS: NOT ACCEPTABLE

Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02 REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
95.00	0	0	0	0	0	0	0	0	0
95.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	0	0	95.00
HOG: 0	BG: 0		NA Deprec. 95.00
			0.00%
			TOTAL 95.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 22/09/2017	Hour : 12:57
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	
	