

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|--------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 164601 KM |
| File nr. : | 1442217 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1APU461 / VF37J9HN0AJ893809 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 01/03/2011 |
| VFS-nr. : | | Color : | WHITE |
| Make + Model : | PEUGEOT / PARTNER | Fuel type : | DIESEL |
| Object nr. : | 76184 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | CEGELEC INDUSTRY | Co2: | 139g/km |
| Driver : | | Remote controls: | 1 |
| Covering : | TISSUE | Number keys : | 1 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | PARTNER TEPEE Confort FAP 75PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1560 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 5 | Number of doors: | 5 |
| HP: | 75 | kW: | 55 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|-----|-----------------------|-------------------------|-----|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | [x] | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | [x] | |
| Fuel card : | | Car radio : | OK | [x] |
| Mobile phone kit : | | Extinguisher : | OK | [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK |
| Jack, wheelspanner : | OK | [x] | Oil level : | OK |
| | | Filled up : | 0 | |

Wheels and tyres: Summer tires

| | | | | | | | | | | | |
|------------|-----|-------|--------|-----|-----|------|-------|-------|----------|----------|------------------|
| Wheel FL: | [x] | FULDA | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | [x] | BROKEN / CRACKED |
| Wheel RL : | [x] | FULDA | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | | |
| Wheel FR : | [x] | FULDA | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | / | Hubcap : | |
| Wheel RR : | [x] | FULDA | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | [x] | |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | / | Hubcap : | | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 55 | R | 15 | V |
| Rear tyre | 205 | 55 | R | 15 | V |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|--|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] FRONT THRESHOLD/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

Interior

- [x] FLOOR BOOT OTHER DAMAGES

Accessories and others

- [x] VEH COVERED WITH STICKERS STICKER(S)

STATUS: NOT ACCEPTABLE

Accessories and others

- [x] OUTSIDE MIRROR RIGHTHAND SIDE BROKEN / CRACKED

| | Repair paint - LI | New paint - E | Depr. | Total |
|-------------------|-------------------|---------------|-------|-----------|
| 1 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |

Others

HUB CAP FL

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 2 0 LU =0.00 EUR | | | 50 % | |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|--------------|------------|-------|-----------|
| 1 | 1 | MIRROR COVER | 90.00 EUR | 50 % | 90.00 EUR |
| Number | Code | Description | Unit price | Depr. | Total |
| 2 | 1 | WHEEL CAP | 22.50 EUR | 50 % | 22.50 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|-------|---|---|---|---|---|---|---|----|
| 114.00 | 22.50 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 57.00 | 11.25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|--------------------|
| 0 | 136.50 | 0 | 136.50 |
| HOG: 0 | BG: 3 | | NA Deprec. 68.25 |
| | | | 0.00% |
| | | | TOTAL 68.25 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 26/09/2017 Hour : 15:18 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |