

www.vabfleetservices.be Date: 09/10/2017 1/4

CVD3PG

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	148833 KM
File nr. :	1445256	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GPP870 / WBA5C11090D03	4087 /	yr of constructionr :	/
E-File nr. :		First registration :	26/03/2014
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 5	Fuel type :	DIESEL
Object nr. :	51411	Fuel:	
Classification:	L	Environment Class:	EURO 5
Customer company:	CEGEKA NV	Co2:	119g/km
Driver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

Variant car:	BERLINE	Engine size:	1995			
Gear box :	Automaat algemeen	Number of places:	5			
Number of gears:		Number of doors:	4			
нр:	136	kW:	100			
Fisc HP		Imported vehicle:				
Animals transported:	No	Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:						

Metallic paint:

Yes



Date: 09/10/2017 www.vabfleetservices.be 2/4

Original registr. number : OK Service manual:

Cert. of conformity: Cert. of reg. / Part 1: OK OK

Cert. of reg. copy / Part 2:

Warning vest: OK

Transport licence: Tax certificate: Navigation CD/SD/DVD

Fuel card : Car radio: OK

Mobile phone kit : Extinguisher: OK

> Warning triangle: OK

> > 0

Insurance certificate:

Oil level: OK OK First aid kit :

Filled up: Jack, wheelspanner :

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre:	OK	2-4 /	Rim:	WHEEL SCRATCHED	/	Hubcap:
Wheel RL:	PIRELLI	Tyre:	OK	2-4 /	Rim:	WHEEL SCRATCHED	/	Hubcap:
Wheel FR:	MICHELIN	Tyre:	OK	2-4 /	Rim:		/	Hubcap:
Wheel RR:	PIRELLI	Tyre:	OK	2-4 /	Rim:		/	Hubcap:
Wheel RES:		Tyre:	OK	/	Rim:		/	Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	225	55	R	17	Y
Rear tyre	225	55	R	17	Y

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



Date: 09/10/2017 3/4 www.vabfleetservices.be

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows [x] REAR BUMPER/RIGHT/RIGHT SCRATCH (WITHOUT PAINT DAMAGE) TE POLIEREN REAR DOOR/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE) TE POLIEREN [x] REAR WINDOW STYLE/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE) [x] REAR MUDGUARD/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE) TE POLIEREN [x] SCRATCH WITH PAINT DAMAGE REAR THRESHOLD/LEFT/REAR [x] REAR DOOR/RIGHT/FRONT DENT [x] FRONT DOOR/LEFT/REAR DENT [x] FRONT DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE) [x] FRONT BUMPER/LEFT/SIDE SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Others

[x]

RIM REAR LEFT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
95.00	0	0	0	0	0	0	0	0	0
95.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
95.00	0	0		95.00
HOG: 0	BG: 2		NA Deprec.	95.00
			0.00%	

TOTAL

95.00



www.vabfleetservices.be Date: 09/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	FANCES		UNDER CONDITION - VEHICLE WET					
Extra Time :	0 min	Waiting time: 0 m Reason:	nin	Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No							
Remark:	ELEKTRONISC	CH ONDERHOUDSBOEKJE / [x]						
Prices in EUR w	ithout VAT							
Authorized by customer :			Executed by VAI	3 Fleet Services				
Remark authorized o	customer :							
Date :	09/10/2017	Hour: 09:44						
Company : Executed by VAB Flo Services	eet							
E-Mail:	@							
Signature authorized b	by customer	1						