

CWVYWO

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	101118 KM
File nr. :	1446400	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
WD8233 / YV1FS31A1F2342978 /		yr of constructionr :	/
E-File nr. :		First registration :	30/09/2014
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / S60	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1984
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :			Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK [x]	2-4/	Rim :			Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :			Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/	Rim :			Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT DOOR/RIGHT/CENTER OTHER DAMAGES POLIEREN

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] ROOF /FRONT/LEFT/CENTER		OTHER DAMAGES	CHEMISCHE INWERKING		
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR

[x] BONNET/CENTER/LEFT		OTHER DAMAGES	SLECHTE HERSTELLING		
Number	Code	Description	Unit price	Depr.	Total
0	0				

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
481.50	95.00	0	0	0	0	0	0	0	0
240.75	95.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	481.50	0	576.50
HOG: 0	BG: 0		NA Deprec. 335.75
			0.00%
			TOTAL 335.75

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : DOCUMENTEN WORDEN NAGESTUURD [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 11/10/2017 Hour : 13:17 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	