

06/10/2017 www.vabfleetservices.be Date: 1/4

CX7RUR

#### [ ] NOT EXECUTED [ ] COLLECTION [X] EFFECTIVE [ ] DELIVERY

[x] = Status Modification

Reg number / Chassis / Ref:

Commissionar: **KBC REMARKETING** Cleanliness: INT: DIRTY [x] EXT: DIRTY [x] Owner: Mileage : 171349 KM

Mileag ref. service :

File nr. : Mileage start / arrival: 1446667 0 / 0

0 yr of constructionr: 1DGK446 / WBAMX11030C975573 /

E-File nr. : First registration: 10/05/2012

VFS-nr.: Color: **BLUE** 

Make + Model : Fuel type : BMW / 5 TOURING **DIESEL** 

Object nr. : Fuel:

**Environment Class:** Classification: EURO 5

Customer company: Co2: KBC GROEP NV 130g/km

Driver : Remote controls: 2

TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0

Vehicle type: 5 TOURING 520d Bus.Ed.St/St 163PK Country registration: **BELGIUM** 

Metallic paint: VAT over the margin - car: No Yes 1995 **BREAK** Variant car: Engine size: Gear box : Number of places: 5 Manueel Number of gears: 6 Number of doors: 5 HP: kW: 163 120 Fisc HP Imported vehicle: No Animals transported: No Smoked in vehicle: No Due date vehicle inspection: Extra set of tires:

No

Use: Unknown

General condition:



www.vabfleetservices.be Date: 06/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :		[x]	Filled up :	0	

### Wheels and tyres: Summer tires

1		[v]	Width			iaht			Type		Dim	Indov
Wheel RES:	[x]		Tyre:	OK		/	Rim:				Hubcap:	
Wheel RR:	[x]	GOODYEAR	Tyre:	OK	[x]	>6 /	Rim:	[x]	WHEEL SCRATCHED	)	Hubcap:	
Wheel FR:	[x]	GOODYEAR	Tyre: [x	] OK	[x]	>6/	Rim:	[x]	WHEEL SCRATCHED	)	Hubcap:	
Wheel RL:	[x]	GOODYEAR	Tyre:	OK	[x]	>6 /	Rim:	[x]	WHEEL SCRATCHED	)	Hubcap:	
Wheel FL:	[x]	GOODYEAR	Tyre:	OK	[x]	>6 /	Rim:	[x]	WHEEL SCRATCHED	)	Hubcap:	

[x]	Width	Height	Туре	Rim	Index
Front tyre	225	55	R	17	Н
Rear tyre	225	55	R	17	Н

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 06/10/2017 3/4

#### STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] FRONT MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

#### STATUS: NOT ACCEPTABLE

#### **Others**

CLEANLINESS INTERIOR

N	umber	Code	Description	Unit price	Depr.	Total
_						
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		58.32 EUR

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
58.32	95.00	0	0	0	0	0	0	0	0
58.32	95.00	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
153.32	0	0	153.32
NA Deprec. 153.32		BG: 2	HOG: 0
0.00%			

TOTAL 153.32



www.vabfleetservices.be Date: 06/10/2017 4/4

[x] = Status Modification

Pictures: No

rictures: N									
CIRCUMS	STANCES	UNDER CONDITION - VEHICLE WET							
Extra Time :	0 min	Waiting time : Reason :	0 min		Towing time : Reason :	0 min			
NOT EXECUTED Reason:	: No				I				
Remark:									
Prices in EUR	without VAT								
Authorized by customer :				Executed by VAB	Fleet Services				
Remark authorized	d customer :								
Date :	06/10/2017	<b>Hour:</b> 11:40	0						
Company:									
Executed by VAB 1 Services	Fleet								
E-Mail :	@								
Signature authorized	d by customer								