

Fisc HP

Animals transported:

General condition:

Due date vehicle inspection:

APPRAISAL

www.vabfleetservices.be Date: 28/08/2017 1/4

CFS95R

[X] EFFECTIVE	[] NOT EXECUTED	[] COLLEC	TION [] DELIVERY
[x] = Status Modification			
Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	1
File nr. :	1433042	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FCY725 / WBA1C91050J	512018 /	yr of constructionr :	/
E-File nr. :		First registration :	28/05/2013
VFS-nr.:		Color :	SILVER
Make + Model :	BMW / 1	Fuel type:	DIESEL
Object nr. :	ONBEKEND	Fuel:	
Classification:		Environment Class:	
Customer company:	WRAK KBC REMARKETING	Co2:	g/km
Driver :		Remote controls:	1
Covering:	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan):	0
Vehicle type :	1 HATCH 116d Eff.Dyn.Ed. 116PK	Country registration :	BELGIUM
VAT over the margin - car:	No	Metallic paint:	
Variant car:	UNKNOWN	Engine size:	
Gear box :		Number of places:	
Number of gears:		Number of doors:	
HP:		kW:	

Imported vehicle:

Smoked in vehicle:

Extra set of tires:

Use:



APPRAISAL

www.vabfleetservices.be Date: 28/08/2017 2/4

Original registr. number : OK Service manual : NOK MISSING/INCOMPLETE Cert. of conformity: Cert. of reg. / Part 1: OK Insurance certificate: Cert. of reg. copy / Part 2: OK Warning vest: Transport licence: Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK Mobile phone kit : Extinguisher: OK Warning triangle: OK OK Oil level: OK First aid kit : OK Filled up: 0 Jack, wheelspanner :

Wheels and tyres: Winter tires

Wheel FL:	MICHELIN	Tyre:	OK	4-6 /	Rim:	/ Hubcap: SCRATCHED
Wheel RL:	MICHELIN	Tyre:	OK	4-6 /	Rim:	/ Hubcap: SCRATCHED
Wheel FR:	MICHELIN	Tyre:	OK	4-6 /	Rim:	/ Hubcap: SCRATCHED
Wheel RR:	MICHELIN	Tyre:	OK	4-6 /	Rim:	/ Hubcap:
Wheel RES:	ANDERE	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	205	55	R	16	M+S
Rear tyre	205	55	R	16	M+S

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

_		Width	Height	Type	Rim	Index
	Front tyre	0	0		0	
	Rear tyre	0	0		0	

Remark:



APPRAISAL

www.vabfleetservices.be Date: 28/08/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

WINDSCREEN/CENTER/LEFT CHIPS

BONNET/CENTER/LEFT DENT

FRONT BUMPER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

	1	2	3	4	5	6	7	8	9	10
	0	0	0	0	0	0	0	0	0	0
ſ	0	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
	0	0	0
NA Deprec.		BG: 0	HOG: 0
0.00%	_		
TOTAL			



APPRAISAL

www.vabfleetservices.be Date: 28/08/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

Extra Time :	0 min	Waiting ti	me: 0 min		Towing time :	0 min
		Reason:	Reason:		Reason:	
NOT EXECUTED :	No	•				
Reason:						
Remark :						
Prices in EUR w	rithout VAT					
Authorized by			_	Executed by VAB Fleet Se	rvices	
customer :						
Remark authorized	customer :					
Date :	28/08/2017	Hour:	13:24			
Company :						
Executed by VAB FI Services	leet					
E-Mail :	@					
Signature authorized	by customer					
<u> </u>						
	ζ					
	\	_				
				ļ		