

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	216608 KM
File nr. :	1448971	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FNH497 / ZFA25000002205270 /		yr of constructionr :	/
E-File nr. :		First registration :	28/08/2013
VFS-nr. :		Color :	WHITE
Make + Model :	FIAT / DUCATO	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	185g/km
Driver :		Remote controls:	1
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	1956
Gear box :	Manueel	Number of places:	3
Number of gears:	5	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	SEMPERIT	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	SEMPERIT	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :			
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	215	70	R	15	
Rear tyre	215	70	R	15	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR LIGHT/RIGHT		HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
9	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	REAR MUDGUARD/LEFT/Front		SCRATCH WITH PAINT DAMAGE	+DEUKEN	
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
8	50 LU =240.00 EUR	0 EUR		50 %	240.00 EUR
[x]	REAR DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE	+DEUK	
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
8	30 LU =144.00 EUR	238.76 EUR		50 %	382.76 EUR
[x]	FRONT DOOR/LEFT/Front		SCRATCH WITH PAINT DAMAGE	+DEUKEN	
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR
[x]	WINDSCREEN/CENTER/RIGHT		HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
5	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT MUDGUARD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUR
[x]	BONNET/RIGHT/CENTER		OTHER DAMAGES		
		Repair paint - LI	New paint - E	Depr.	Total
3	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR

[x]	LIGHTS/LEFT/FRONT	HOLE/CRACK/TORN			
			Repair paint - LI	New paint - E	Depr. Total
4	0 LU =0.00 EUR		0 EUR		50 %
4	20 LU =96.00 EUR		0 EUR		50 % 96.00 EUR

[x]	FRONT BUMPER/CENTER/RIGHT	HOLE/CRACK/TORN			
			Repair paint - LI	New paint - E	Depr. Total
2	0 LU =0.00 EUR		0 EUR		50 %
2	20 LU =96.00 EUR		0 EUR		50 % 96.00 EUR

Interior

[x]	BOOT LID IN	OTHER DAMAGES			
			Repair paint - LI	New paint - E	Depr. Total
10	0 LU =0.00 EUR		0 EUR		50 %
10	30 LU =144.00 EUR		0 EUR		50 % 144.00 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	BROKEN / CRACKED			
			Repair paint - LI	New paint - E	Depr. Total
10	0 LU =0.00 EUR		0 EUR		50 %

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	BROKEN / CRACKED			
			Repair paint - LI	New paint - E	Depr. Total
10	0 LU =0.00 EUR		0 EUR		50 %
10	5 LU =24.00 EUR		0 EUR		50 % 24.00 EUR

Others

	HUB CAP FL				
			Repair paint - LI	New paint - E	Depr. Total
1	0 LU =0.00 EUR				50 %

	HUB CAP REAR L				
			Repair paint - LI	New paint - E	Depr. Total
1	0 LU =0.00 EUR				50 %

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
1	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
1	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
2	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
4	1	LIGHT UNIT	225.00 EUR	50 %	225.00 EUR
5	1	WIND SCREEN	275.40 EUR	50 %	275.40 EUR
8	1	DOOR REAR RIGHT	275.40 EUR	50 %	275.40 EUR
8	1	FENDER REAR RIGHT	441.00 EUR	50 %	441.00 EUR
9	1	REAR LIGHT	67.50 EUR	50 %	67.50 EUR
10	1	MIRROR COVER	90.00 EUR	50 %	90.00 EUR
10	1	MIRROR GLASS	13.50 EUR	50 %	13.50 EUR
10	1	6 PANELEN	120.00 EUR	50 %	120.00 EUR

1	2	3	4	5	6	7	8	9	10
67.50	398.40	96.00	321.00	395.40	165.13	238.76	1339.16	91.50	391.50
33.75	199.20	48.00	160.50	197.70	82.56	119.38	669.58	45.75	195.75

INNOVATIVE	TRADITIONAL	GENERAL	
0	3504.35	0	3504.35
HOG: 0	BG: 3		NA Deprec. 1752.18
			0.00%
			TOTAL 1752.18

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/10/2017 Hour : 11:44 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	