

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	239381 KM
<b>File nr. :</b>	1447177	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
497BKV / WF0XXXTTFXAL57633 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	23/03/2010
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	FORD / TRANSIT	<b>Fuel type :</b>	
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>	DELIVERY VAN B	<b>Environment Class:</b>	
<b>Customer company :</b>	WRAK KBC REMARKETING	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	3
<b>Number of gears:</b>	6	<b>Number of doors:</b>	4
<b>HP:</b>		<b>kW:</b>	
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :		Service manual :	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Winter tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	DUNLOP	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]	DUNLOP	Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	75	R	16	M+S
Rear tyre	215	75	R	16	M+S

Remark :

## Wheels and tyres:

Wheel FL:			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RL :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel FR :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RR :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RES:			Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR DOOR/CENTER/RIGHT DENT
- [x] FRONT DOOR/RIGHT/REAR DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
3	0 LU =0.00 EUR		231.15 EUR		50 %
					231.15 EUR
[x]	REAR BUMPER/SIDE/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>
					<b>Total</b>
4	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	
					110.64 EUR
[x]	REAR DOOR/RIGHT/FRONT	OTHER DAMAGES			ROEST
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
2	0 LU =0.00 EUR		238.76 EUR		50 %
					238.76 EUR
[x]	REAR THRESHOLD/RIGHT/FRONT	OTHER DAMAGES			ROEST
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
2	0 LU =0.00 EUR		232.88 EUR		50 %
					232.88 EUR
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
3	0 LU =0.00 EUR		238.76 EUR		50 %
					238.76 EUR
[x]	FRONT THRESHOLD/LEFT/FRONT	OTHER DAMAGES			ROEST
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
2	0 LU =0.00 EUR		232.88 EUR		50 %
					232.88 EUR
[x]	ROOF STYLE/FRONT/LEFT/CENTER	OTHER DAMAGES			ROEST
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
2	0 LU =0.00 EUR		165.14 EUR		50 %
					165.14 EUR
[x]	BONNET/CENTER/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
1	0 LU =0.00 EUR		217.56 EUR		50 %
					217.56 EUR

## Accessories and others

[x] FOG LAMPS

BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
5 10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1	FOG LAMP	67.50 EUR	50 %	67.50 EUR

1	2	3	4	5	6	7	8	9	10
217.56	869.66	469.91	110.64	115.50	0	0	0	0	0
108.78	434.83	234.96	110.64	57.75	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
110.64	1672.63	0	<b>1783.27</b>
HOG: 0	BG: 3		NA Deprec. 946.96
			0.00%
			<b>TOTAL 946.96</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 09/10/2017 <b>Hour :</b> 12:12 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	