

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	104164 KM
File nr. :	1366026	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FJB578 / WVVZZZAUZEW034602 /		yr of constructionr :	/
E-File nr. :		First registration :	12/07/2013
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	713108	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	HANDSON & PARTNERS NV	Co2:	98g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GOLF BER Trendline 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	KUM-HO	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel RL :	BRIDGESTONE	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel FR :	KUM-HO	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel RR :	BRIDGESTONE	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x] ANDERE	Tyre :	OK	[x] >6/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	195	65	R	16	M+S
Rear tyre	195	65	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	DENT		
[x]	REAR MUDGUARD/LEFT/CENTER	DENT		
[x]	REAR MUDGUARD/LEFT/FRONT	DENT		
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)		
[x]	FRONT DOOR/LEFT/CENTER	DENT		
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)		
[x]	ROOF/CENTER/LEFT	OTHER DAMAGES	OVB POLIJSTEN	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/REAR	DENT			
Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Interior

[x]	BOOT LID IN	CUT / TORN			
Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

1	2	3	4	5	6	7	8	9	10
110.64	63.00	0	0	0	0	0	0	0	0
110.64	63.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
173.64	0	0	173.64
HOG: 0	BG: 0		NA Deprec. 173.64
			0.00%
			TOTAL 173.64

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 09/02/2017 Hour : 13:23 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	