

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	107655 KM
File nr. :	1446602	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FTS377 / WBA1C91030J517105 /		yr of constructionr :	/
E-File nr. :		First registration :	22/10/2013
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 1 HATCH	Fuel type :	DIESEL
Object nr. :	713108	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	PWC BUSINESS SERVICES CVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RL :	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel FR :	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RR :	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT		SCRATCH WITH PAINT DAMAGE					
		Repair paint - LI	New paint - E	Depr.	Total			
5	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR			
[x]	REAR MUDGUARD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE					
		Repair paint - LI	New paint - E	Depr.	Total			
3	0 LU =0.00 EUR	369.84 EUR		50 %	369.84 EUR			
[x]	REAR WINDOW/LEFT		SCRATCH WITH PAINT DAMAGE					
		Repair paint - LI	New paint - E	Depr.	Total			
6	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR			
[x]	REAR DOOR/LEFT/CENTER		DENT					
	Number	Code	Description	Unit price	Depr.	Total		
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR		
[x]	ROOF/CENTER/LEFT		OTHER DAMAGES		CHEMISCHE INWERKING			
		Repair paint - LI	New paint - E	Depr.	Total			
4	0 LU =0.00 EUR	577.80 EUR		50 %	577.80 EUR			
[x]	BONNET/CENTER/LEFT		OTHER DAMAGES		CHEMISCHE INWERKING			
		Repair paint - LI	New paint - E	Depr.	Total			
4	0 LU =0.00 EUR	348.09 EUR		50 %	348.09 EUR			
[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE					
		Repair paint - LI	New paint - E	Depr.	Total			
1	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR			

Pieces

Number	Code	Description	Unit price	Depr.	Total
6	1	BACK WINDOW	300.00 EUR	50 %	300.00 EUR

1	2	3	4	5	6	7	8	9	10
254.16	63.00	369.84	925.89	254.16	420.00	0	0	0	0
127.08	63.00	184.92	462.94	127.08	210.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	2224.05	0	2287.05
HOG: 0	BG: 2		NA Deprec. 1175.02
			0.00%
			TOTAL 1175.02

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 16:31 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	