

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	196247 KM
File nr. :	1450884	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
YD4260 / WAUZZZ4G6EN184201 /		yr of constructionr :	/
E-File nr. :		First registration :	25/09/2014
VFS-nr. :		Color :	BROWN
Make + Model :	AUDI / A6 AVANT	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	L	Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	177	kW:	130
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :	[x]	Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :			Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE	HERSTELD	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR
[x]	FRONT THRESHOLD/LEFT/FRONT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	372.60 EUR		50 %	372.60 EUR
[x]	FRONT BUMPER/LEFT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
1	20 LU =96.00 EUR	0 EUR	282.96 EUR	50 %	378.96 EUR

Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FRONT BUMPER	483.84 EUR	50 %	483.84 EUR

1	2	3	4	5	6	7	8	9	10
862.80	372.60	254.16	190.00	0	0	0	0	0	0
431.40	186.30	127.08	190.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	1489.56	0	1679.56
HOG: 0	BG: 2		NA Deprec. 934.78
			0.00%
			TOTAL 934.78

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : DOCUMENTEN WORDEN NAGESTUURD [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 10:39 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	