

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	163789 KM
File nr. :	1446589	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EYC098 / WAUZZZ8R9DA085082 /		yr of constructionr :	/
E-File nr. :		First registration :	18/04/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / Q5	Fuel type :	DIESEL
Object nr. :	45730	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KPMG ADVISORY CVBA	Co2:	139g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	Q5 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	Yes
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] FULDA	Tyre : OK [x] 2-4/	Rim :	Hubcap :
Wheel RL : [x] FULDA	Tyre : OK [x] 2-4/	Rim :	Hubcap :
Wheel FR : [x] FULDA	Tyre : [x] OK [x] 2-4/	Rim :	Hubcap :
Wheel RR : [x] FULDA	Tyre : OK [x] 2-4/	Rim :	Hubcap :
Wheel RES: [x]	Tyre : OK /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	65	R	17	WINTER ZR
Rear tyre	235	65	R	17	WINTER ZR

Remark :

Wheels and tyres:

Wheel FL:	Tyre : OK /	Rim :	Hubcap :
Wheel RL :	Tyre : OK /	Rim :	Hubcap :
Wheel FR :	Tyre : OK /	Rim :	Hubcap :
Wheel RR :	Tyre : OK /	Rim :	Hubcap :
Wheel RES:	Tyre : OK /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE		
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE	HERSTELD	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES		INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	348.09 EUR		50 %	348.09 EUR

Interior

[x]	FLOOR FL	BURNT				
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR		43.92 EUR
	Number	Code	Description	Unit price	Depr.	Total
1	I 3	i-vab-inttap-02	SUPPL REPAIR CARPET	18.00 EUR		54.00 EUR
[x]	SEAT FL	STAIN				
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

1	2	3	4	5	6	7	8	9	10
112.50	348.09	254.16	0	0	0	0	0	0	0
112.50	174.04	127.08	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
112.50	602.25	0	714.75
HOG: 0	BG: 2		NA Deprec. 413.62
			0.00%
			TOTAL 413.62

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 09:47 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	