

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|--------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 69161 KM |
| File nr. : | 1446498 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FCW705 / WBA1C91050J510530 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 28/05/2013 |
| VFS-nr. : | | Color : | BROWN |
| Make + Model : | BMW / 1 | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | BELGACOM INS/FLEET NV | Co2: | 99g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | TRUCK, LORRY | Seats (minivan) : | 0 |
| Vehicle type : | 1 HATCH 116d Eff.Dyn.Ed. 116PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1598 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 116 | kW: | 85 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | |
|------------------------------|--------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | |
| Cert. of reg. / Part 1: | OK [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | |
| Warning vest : | OK [x] | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | |
| Fuel card : | | Car radio : | OK [x] |
| Mobile phone kit : | | Extinguisher : | OK [x] |
| First aid kit : | OK [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | Oil level : | |
| | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | | | |
|------------|-----|-------------|--------|-----|-----|------|-------|-------|---|----------|-----|-----------|
| Wheel FL: | [x] | BRIDGESTONE | Tyre : | OK | [x] | 4-6/ | Rim : | [x] | / | Hubcap : | [x] | SCRATCHED |
| Wheel RL : | [x] | BRIDGESTONE | Tyre : | OK | [x] | 4-6/ | Rim : | | / | Hubcap : | [x] | SCRATCHED |
| Wheel FR : | [x] | BRIDGESTONE | Tyre : | [x] | OK | [x] | 4-6/ | Rim : | | Hubcap : | [x] | SCRATCHED |
| Wheel RR : | [x] | BRIDGESTONE | Tyre : | OK | [x] | 4-6/ | Rim : | | / | Hubcap : | [x] | SCRATCHED |
| Wheel RES: | [x] | ANDERE | Tyre : | OK | | / | Rim : | | / | Hubcap : | | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 55 | R | 16 | W |
| Rear tyre | 205 | 55 | R | 16 | W |

Remark :

Wheels and tyres:

| | | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|--|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : | |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : | |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : | |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : | |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | |
|-----|---------------------------|---------------------------|----------|
| [x] | REAR THRESHOLD/LEFT/REAR | SCRATCH WITH PAINT DAMAGE | INSTAP |
| [x] | REAR THRESHOLD/RIGHT/REAR | SCRATCH WITH PAINT DAMAGE | INSTAP |
| [x] | FRONT DOOR/LEFT/REAR | DENT | |
| [x] | WINDSCREEN/CENTER/LEFT | WINDOW DAMAGE | HERSTELD |
| [x] | FRONT DOOR/RIGHT/REAR | DENT | |
| [x] | BONNET/CENTER/LEFT | DENT | |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | |
|-----|---------------------------|---------------------------|----------------------|
| [x] | REAR BUMPER /LEFT/CORNER | SCRATCH WITH PAINT DAMAGE | MEERDERE |
| | | Repair paint - LI | New paint - E |
| | | Depr. | Total |
| | 2 0 LU =0.00 EUR | 211.80 EUR | 50 % |
| | | | 211.80 EUR |
| [x] | REAR LIGHT/RIGHT | HOLE/CRACK/TORN | |
| | | Repair paint - LI | New paint - E |
| | | Depr. | Total |
| | 4 5 LU =24.00 EUR | 0 EUR | 50 % |
| | | | 24.00 EUR |
| [x] | REAR WINDOW/LEFT | WINDOW DAMAGE | POL KRASSEN |
| | Number | Code | Description |
| | Unit price | Depr. | Total |
| | 3 | I 1 i-vab-herstr-01 | WINDOW REPAIR |
| | | | 58.80 EUR |
| | | | 58.80 EUR |
| | Number | Code | Description |
| | Unit price | Depr. | Total |
| | 3 | I 2 i-vab-herstr-02 | SUPPL WINDOW REPAIR |
| | | | 29.40 EUR |
| | | | 58.80 EUR |
| [x] | FRONT BUMPER/RIGHT/CORNER | SCRATCH WITH PAINT DAMAGE | MEERDERE |
| | | Repair paint - LI | New paint - E |
| | | Depr. | Total |
| | 1 0 LU =0.00 EUR | 211.80 EUR | 50 % |
| | | | 211.80 EUR |

Others

HUB CAP FL

| | | | |
|--|------------------|--------------------------|----------------------|
| | | Repair paint - LI | New paint - E |
| | | Depr. | Total |
| | 5 0 LU =0.00 EUR | | 50 % |

HUB CAP REAR L

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 5 0 LU =0.00 EUR | | | 50 % | |

HUB CAP REAR RIGHT

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 5 0 LU =0.00 EUR | | | 50 % | |

HUB CAP FR

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 5 0 LU =0.00 EUR | | | 50 % | |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 4 | 1 | REAR LIGHT | 90.00 EUR | 50 % | 90.00 EUR |
| 5 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |
| 5 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |
| 5 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |
| 5 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|--------|---|---|---|---|----|
| 211.80 | 211.80 | 117.60 | 114.00 | 120.00 | 0 | 0 | 0 | 0 | 0 |
| 105.90 | 105.90 | 117.60 | 57.00 | 60.00 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 117.60 | 657.60 | 0 | 775.20 |
| HOG: 0 | BG: 0 | | NA Deprec. 446.40 |
| | | | 0.00% |
| | | | TOTAL 446.40 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 09:45 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |