

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	129830 KM
File nr. :	1446393	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPG623 / WBA1C91060J516417 /		yr of constructionr :	/
E-File nr. :		First registration :	13/09/2013
VFS-nr. :		Color :	BLUE L
Make + Model :	BMW / 1	Fuel type :	DIESEL
Object nr. :	6276	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SIEMENS INDUSTRY SOFTWARE NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	1 HATCH 116d Eff.Dyn.Ed. 116PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :		
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED / Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	ROOF STYLE/CENTER/LEFT	DENT
[x]	ROOF/CENTER/LEFT	DENT
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS
[x]	FRONT BUMPER/CENTER/RIGHT	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE										
		<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>0 LU =0.00 EUR</td> <td>211.80 EUR</td> <td>50 %</td> <td>211.80 EUR</td> </tr> </tbody> </table>		Repair paint - LI	New paint - E	Depr.	Total	4	0 LU =0.00 EUR	211.80 EUR	50 %	211.80 EUR
	Repair paint - LI	New paint - E	Depr.	Total								
4	0 LU =0.00 EUR	211.80 EUR	50 %	211.80 EUR								
[x]	REAR WINDOW/LEFT	WINDOW DAMAGE										
		<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>3</td> <td>25 LU =120.00 EUR</td> <td>0 EUR</td> <td>50 %</td> <td>120.00 EUR</td> </tr> </tbody> </table>		Repair paint - LI	New paint - E	Depr.	Total	3	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR
	Repair paint - LI	New paint - E	Depr.	Total								
3	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR								
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE										
		<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>25 LU =120.00 EUR</td> <td>0 EUR</td> <td>50 %</td> <td>120.00 EUR</td> </tr> </tbody> </table>		Repair paint - LI	New paint - E	Depr.	Total	2	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR
	Repair paint - LI	New paint - E	Depr.	Total								
2	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR								

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR
3	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
0	487.20	370.00	211.80	95.00	0	0	0	0	0
0	243.60	185.00	105.90	95.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	1069.00	0	1164.00
HOG: 0	BG: 0		NA Deprec. 629.50
			0.00%
			TOTAL 629.50

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 12:18 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	