

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	153049 KM
File nr. :	1445329	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FHW460 / WBA1C91020J511912 /		yr of constructionr :	/
E-File nr. :		First registration :	03/07/2013
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / 1	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	1 HATCH 116d Eff.Dyn.Ed. 116PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT DOOR/LEFT/REAR DENT
- [x] FRONT BUMPER/RIGHT/CORNER SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

Number	Code	Description	Unit price	Depr.	Total
[x]		REAR MUDGUARD/LEFT/REAR OTHER DAMAGES SLECHT HERSTELD			
0	0				
[x]		WINDSCREEN/CENTER/LEFT WINDOW DAMAGE			
2	11 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
[x]		BONNET/CENTER/RIGHT OTHER DAMAGES INWERKING			
		Repair paint - LI New paint - E		Depr.	Total
1	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]		ROOF/CENTER/LEFT OTHER DAMAGES INWERKING			
		Repair paint - LI New paint - E		Depr.	Total
1	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR

Others

		HUB CAP REAR L			
		Repair paint - LI New paint - E		Depr.	Total
3	0 LU =0.00 EUR			50 %	
		HUB CAP REAR RIGHT			
		Repair paint - LI New paint - E		Depr.	Total
3	0 LU =0.00 EUR			50 %	
		HUB CAP FR			
		Repair paint - LI New paint - E		Depr.	Total
3	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
3	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
3	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
771.58	58.80	90.00	0	0	0	0	0	0	0
385.79	58.80	45.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.80	861.58	0	920.38
HOG: 0	BG: 0		NA Deprec. 489.59
			0.00%
			TOTAL 489.59

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/10/2017 Hour : 11:20 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	