

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	108670 KM
File nr. :	1447982	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FRF604 / WBA3D91060J412967 /		yr of constructionr :	/
E-File nr. :		First registration :	01/10/2013
VFS-nr. :		Color :	WHITE
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	DELAWARE CONSULTING BVBA	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 BER 316d 116PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	OK
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	HANGKOOK	Tyre :	OK	[x]	4-6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	HANGKOOK	Tyre :	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	HANGKOOK	Tyre :	[x] OK	[x]	4-6/	Rim :	[x] WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	HANGKOOK	Tyre :	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED	/	Hubcap :
Wheel RES:		Tyre :	OK		/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	W
Rear tyre	205	60	R	16	W

Remark : REPARATIEKIT AANWEZIG

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE
[x]	WINDSCREEN/RIGHT	WINDOW DAMAGE
[x]	FRONT MUDGUARD/RIGHT/CENTER	DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
		Repair paint - LI New paint - E Depr. Total
3	0 LU =0.00 EUR	211.80 EUR 50 % 211.80 EUR
[x]	REAR THRESHOLD/LEFT/FRONT	DENT
		Repair paint - LI New paint - E Depr. Total
2	10 LU =48.00 EUR	310.50 EUR 50 % 358.50 EUR
[x]	FRONT THRESHOLD/LEFT/REAR	DENT
		Repair paint - LI New paint - E Depr. Total
2	10 LU =48.00 EUR	310.50 EUR 50 % 358.50 EUR
[x]	FRONT THRESHOLD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
		Repair paint - LI New paint - E Depr. Total
4	0 LU =0.00 EUR	310.50 EUR 50 % 310.50 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE MEERDERE
		Repair paint - LI New paint - E Depr. Total
1	0 LU =0.00 EUR	211.80 EUR 50 % 211.80 EUR

Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	717.00	211.80	310.50	95.00	0	0	0	0	0
105.90	358.50	105.90	155.25	95.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	1451.10	0	1546.10
HOG: 0	BG: 0		NA Deprec. 820.55
			0.00%
			TOTAL 820.55

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : OHB IS DIGITAAL [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 09:41 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	