

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	85799 KM
<b>File nr. :</b>	1443902	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FSL434 / WBA5C31020D046447 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	10/10/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE
<b>Make + Model :</b>	BMW / 5	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	73401	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 6
<b>Customer company :</b>	EUROP ASSISTANCE BELGIUM NV/SA	<b>Co2:</b>	119g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	5 BER 520dA 163PK Aut.	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1995
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	163	<b>kW:</b>	120
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :			/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR DOOR/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT		DENT					
				<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>		<b>Total</b>
5	0 LU =0.00 EUR			254.16 EUR		50 %		254.16 EUR
[x]	FRONT THRESHOLD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE			+DEUKEN BINNENIN		
				<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>		<b>Total</b>
8	0 LU =0.00 EUR			372.60 EUR		50 %		372.60 EUR
[x]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE					
				<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>		<b>Total</b>
4	0 LU =0.00 EUR			382.02 EUR		50 %		382.02 EUR
[x]	FRONT DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE					
	<b>Number</b>	<b>Code</b>	<b>Description</b>			<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
0	0							
[x]	FRONT DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE					
				<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>		<b>Total</b>
6	0 LU =0.00 EUR			382.02 EUR		50 %		382.02 EUR
[x]	FRONT MUDGUARD/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE			+DEUK		
				<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>		<b>Total</b>
7	0 LU =0.00 EUR			264.21 EUR		50 %		264.21 EUR
[x]	FRONT BUMPER/LEFT/CORNER		SCRATCH WITH PAINT DAMAGE					
				<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>		<b>Total</b>
3	0 LU =0.00 EUR			254.16 EUR		50 %		254.16 EUR

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 5	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		72.90 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
72.90	285.00	254.16	382.02	254.16	382.02	264.21	372.60	0	0
72.90	285.00	127.08	191.01	127.08	191.01	132.10	186.30	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
357.90	1909.17	0	<b>2267.07</b>
HOG: 0	BG: 2		NA Deprec. 1312.48
			0.00%
			<b>TOTAL 1312.48</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 18/10/2017 <b>Hour :</b> 08:01 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	