

D2MY00

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: DIRTY [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 26619 KM |
| File nr. : | 1450904 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1PYU258 / ZCFC635A605116216 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 13/10/2016 |
| VFS-nr. : | | Color : | WHITE |
| Make + Model : | IVECO / DAILY | Fuel type : | DIESEL |
| Object nr. : | ONBEKEND | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | ONBEKEND | Co2: | 227g/km |
| Driver : | | Remote controls: | 1 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | |
| Variant car: | BESTELWAGEN | Engine size: | 2998 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 4 |
| HP: | 146 | kW: | 107 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |
| General condition: | | | |

| | | | |
|------------------------------|--------|-------------------------|--------|
| Original registr. number : | | Service manual : | |
| Cert. of reg. / Part 1: | OK [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | |
| Warning vest : | | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | |
| Fuel card : | | Car radio : | OK [x] |
| Mobile phone kit : | | Extinguisher : | OK [x] |
| First aid kit : | OK [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | Oil level : | OK [x] |
| | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | |
|------------|-----|-------------|--------|------------|------|-------|---|----------|
| Wheel FL: | [x] | CONTINENTAL | Tyre : | OK [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RL : | [x] | CONTINENTAL | Tyre : | OK [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel FR : | [x] | CONTINENTAL | Tyre : | [x] OK [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RR : | [x] | CONTINENTAL | Tyre : | OK [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RES: | [x] | CONTINENTAL | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 195 | 75 | R | 16 | R |
| Rear tyre | 195 | 75 | R | 16 | R |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

Conclusion

Bodywork \& windows

[x] FRONT DOOR/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR LIGHT/LEFT/CORNER HOLE/CRACK/TORN

| | Repair paint - LI | New paint - E | Depr. | Total |
|-------------------|-------------------|---------------|-------|-----------|
| 3 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |

[x] REAR BUMPER/RIGHT/RIGHT DENT

| | Repair paint - LI | New paint - E | Depr. | Total |
|--------------------|-------------------|---------------|-------|-----------|
| 1 15 LU =72.00 EUR | 0 EUR | | 50 % | 72.00 EUR |

[x] REAR DOOR/CENTER/RIGHT DENT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-------------------|---------------|------------|-------|-----------|
| 2 | I 1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |

[x] REAR MUDGUARD/LEFT/REAR SCRATCH WITH PAINT DAMAGE

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|------------|
| 3 0 LU =0.00 EUR | 231.15 EUR | | 50 % | 231.15 EUR |

[x] FRONT MUDGUARD/RIGHT/FRONT DENT

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|------------|
| 4 0 LU =0.00 EUR | 165.13 EUR | | 50 % | 165.13 EUR |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|------------|
| 1 | 1 | REAR BUMPER | 257.40 EUR | 50 % | 257.40 EUR |

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 3 | 1 | REAR LIGHT | 67.50 EUR | 50 % | 67.50 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|-------|--------|--------|---|---|---|---|---|----|
| 329.40 | 63.00 | 322.65 | 165.13 | 0 | 0 | 0 | 0 | 0 | 0 |
| 164.70 | 63.00 | 161.32 | 82.56 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 63.00 | 817.18 | 0 | 880.18 |
| HOG: 0 | BG: 3 | | NA Deprec. 471.59 |
| | | | 0.00% |
| | | | TOTAL 471.59 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |