

18/10/2017 www.vabfleetservices.be Date: 1/4

D0BNGK

[] NOT EXECUTED [X] EFFECTIVE [X] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 119324 KM File nr. : Mileage start / arrival: 0 / 01449047 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1EBC893 / W0LGM6EJ4D1016594 / E-File nr. : First registration: 09/10/2012 Color: VFS-nr.: **BLACK** Make + Model : Fuel type : OPEL / INSIGNIA **DIESEL** Object nr. : Fuel: 48506 Classification: **Environment Class:** EURO 5 Customer company: Co2: TMVW CVBA 114g/km Driver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: **VEHICLE** Seats (minivan): 0 Vehicle type: INSIGNIA BER ecoFL.Edit.150Ys 110PK Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes					
Variant car:		Engine size:	1956					
Gear box :	Manueel	Number of places:	5					
Number of gears:	6	Number of doors:	5					
HP:	110	kW:	81					
Fisc HP		Imported vehicle:						
Animals transported:	No	Smoked in vehicle:	No					
Due date vehicle inspection:		Extra set of tires:						
		Use:	Unknown					
General condition:	General condition:							



www.vabfleetservices.be Date: 18/10/2017 2/4

Original registr. number : OK Service manual : OK [x] Cert. of conformity: Cert. of reg. / Part 1: OK Insurance certificate: Cert. of reg. copy / Part 2: OK [x]Warning vest: Transport licence: Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK [x] Extinguisher: Mobile phone kit : OK [x] Warning triangle: OK [x] OK Oil level: OK First aid kit : [x] [x] Filled up: 0 Jack, wheelspanner :

Wheels and tyres: Summer tires

		[x]	Width			Не	eight			Туре		Rim	Index
Wheel RES:	[x]		Tyre:	(OK		/	Rim:				/ Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:	(OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	[x] (OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel RL:	[x]	MICHELIN	Tyre:	(OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel FL:	[x]	MICHELIN	Tyre:	(OK	[x]	2-4 /	Rim:				/ Hubcap:	

] Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	Y
Rear tyre	225	55	R	17	Y

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/	Hubcap :
Wheel FR:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/	Hubcap :
Wheel RES:	Tyre:	OK	/	Rim:	/	Hubcap :
1						

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 18/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/LEFT/CENTER DENT

[x] FRONT BUMPER/LEFT/CORNER SCRATCH (WITHOUT PAINT DAMAGE)

Interior

[x] SEAT FL CUT / TORN

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/SIDE/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

 Repair paint - LI
 New paint - E
 Depr.
 Total

 1 0 LU = 0.00 EUR
 211.80 EUR
 50 %
 211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	0	0	0	0	0	0	0	0	0
105.90	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
211.80	0	211.80	0
NA Deprec. 105.90		BG: 0	HOG: 0
0.000/			

0.00%
TOTAL 105.90



www.vabfleetservices.be Date: 18/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS'	TANCES			NORMAL CONCLUSION					
Extra Time :	0 min	Waiting ti Reason :	Waiting time: 0 min Reason:		Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No								
Remark :									
Prices in EUR w	vithout VAT								
Authorized by customer :				Executed by VAB Flo	eet Services				
Remark authorized	customer :								
Date :	18/10/2017	Hour :	12:50						
Company:									
Executed by VAB Fl Services	leet								
E-Mail :	@								
Signature authorized	by customer		_						
/									