

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	86283 KM
File nr. :	1447632	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DIP147 / W0L6VXC1AC9511304 /		yr of constructionr :	/
E-File nr. :		First registration :	28/05/2012
VFS-nr. :		Color :	WHITE
Make + Model :	OPEL / COMBO CARGO	Fuel type :	DIESEL
Object nr. :	11905	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SIMAC NV	Co2:	129g/km
Driver :		Remote controls:	0
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	COMBO COMBI LWB St/St(EU5)90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1248
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	BROKEN / CRACKED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :			
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	60	R	16	T
Rear tyre	195	60	R	16	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR WINDOW STYLE/CENTER/LEFT/UP	DENT	EN KRASSEN
[x]	REAR DOOR/LEFT/CENTER	DENT	
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	WINDOW STYLE/FRONT DOOR/RIGHT/FRONT	DENT	

Interior

[x]	DASHBORD	SCRATCHED
[x]	SEAT FR	STAIN
[x]	BOOT LID IN	SCRATCHED

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
-----	---------------------------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR
[x]	REAR MUDGUARDL/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
5	20 LU =96.00 EUR	231.15 EUR		50 %	327.15 EUR
[x]	FRONT DOOR/LEFT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	30 LU =144.00 EUR	238.76 EUR		50 %	382.76 EUR
[x]	WINDSCREEN/RIGHT	WINDOW DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
9	I 1 i-vab-herstr-01	WINDOW REPAIR		58.80 EUR	58.80 EUR

[x]					
		Repair paint - LI	New paint - E	Depr.	Total
2	FRONT MUDGUARD/LEFT/REAR	0 EUR	177.91 EUR	50 %	273.91 EUR
	20 LU =96.00 EUR				

Interior

[x]					
		Repair paint - LI	New paint - E	Depr.	Total
1	LUGGAGE COVER	0 EUR		50 %	
	0 LU =0.00 EUR				

Accessories and others

[x]					
		Repair paint - LI	New paint - E	Depr.	Total
6	OUTSIDE MIRROR LEFTHAND SIDE	0 EUR		50 %	48.00 EUR
	10 LU =48.00 EUR				

[x]					
		Repair paint - LI	New paint - E	Depr.	Total
7	OUTSIDE MIRROR RIGHTHAND SIDE	0 EUR		50 %	48.00 EUR
	10 LU =48.00 EUR				

[x]					
		Repair paint - LI	New paint - E	Depr.	Total
10	SIDE PROTECTION	0 EUR		50 %	24.00 EUR
	5 LU =24.00 EUR				

Others

		Repair paint - LI	New paint - E	Depr.	Total
8	HUB CAP FL			50 %	
	0 LU =0.00 EUR				

		Repair paint - LI	New paint - E	Depr.	Total
8	HUB CAP REAR L			50 %	
	0 LU =0.00 EUR				

		Repair paint - LI	New paint - E	Depr.	Total
8	HUB CAP FR			50 %	
	0 LU =0.00 EUR				

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	LUGGAGE COVER	180.00 EUR	50 %	180.00 EUR
2	1	FENDER FL	129.60 EUR	50 %	129.60 EUR
3	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR
4	1	ACHTERPANEEL	120.00 EUR	50 %	120.00 EUR
6	1	MIRROR	90.00 EUR	50 %	90.00 EUR
7	1	MIRROR	90.00 EUR	50 %	90.00 EUR
7	1	MIRROR GLASS	13.50 EUR	50 %	13.50 EUR
7	1	INDICATOR	11.25 EUR	50 %	11.25 EUR
8	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
8	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
10	2	SIDE PROTECTION	10.80 EUR	50 %	21.60 EUR
8	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

1	2	3	4	5	6	7	8	9	10
180.00	786.27	329.40	144.00	327.15	138.00	162.75	67.50	58.80	45.60
90.00	393.14	164.70	72.00	163.58	69.00	81.38	33.75	58.80	22.80

INNOVATIVE	TRADITIONAL	GENERAL	
58.80	2180.67	0	2239.47
HOG: 0	BG: 3		NA Deprec. 1149.14
			0.00%
			TOTAL 1149.14

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 10:45 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	