

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	125080 KM
<b>File nr. :</b>	1446233	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DFS706 / VF1JZ14B646558887 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	07/05/2012
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	RENAULT / GRAND SCENIC	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	63544	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	DE VIJVER MEDIA	<b>Co2:</b>	105g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	7 [x]
<b>Vehicle type :</b>	GR.SCENIC Energ.Dynamique 7pl.FAP 110PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1461
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	110	<b>kW:</b>	81
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE	
		<b>Repair paint - LI</b> <b>New paint - E</b> <b>Depr.</b> <b>Total</b>	
3	0 LU =0.00 EUR	211.80 EUR	50 %      211.80 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT	
		<b>Repair paint - LI</b> <b>New paint - E</b> <b>Depr.</b> <b>Total</b>	
4	50 LU =240.00 EUR	0 EUR      403.51 EUR	50 %      643.51 EUR
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
		<b>Repair paint - LI</b> <b>New paint - E</b> <b>Depr.</b> <b>Total</b>	
4	15 LU =72.00 EUR	318.35 EUR	50 %      390.35 EUR
[x]	ROOF/FRONT/CENTER/RIGHT	OTHER DAMAGES	CHEMSICHE INWERKING
		<b>Repair paint - LI</b> <b>New paint - E</b> <b>Depr.</b> <b>Total</b>	
2	0 LU =0.00 EUR	481.50 EUR	50 %      481.50 EUR
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
		<b>Repair paint - LI</b> <b>New paint - E</b> <b>Depr.</b> <b>Total</b>	
4	0 LU =0.00 EUR	318.35 EUR	50 %      318.35 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE	
		<b>Repair paint - LI</b> <b>New paint - E</b> <b>Depr.</b> <b>Total</b>	
1	0 LU =0.00 EUR	211.80 EUR	50 %      211.80 EUR

### Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	FENDER REAR RIGHT	588.00 EUR	50 %	588.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	481.50	211.80	1940.21	190.00	0	0	0	0	0
105.90	240.75	105.90	970.10	190.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	2845.31	0	<b>3035.31</b>
HOG: 0	BG: 0		NA Deprec. 1612.66
			0.00%
			<b>TOTAL 1612.66</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 16/10/2017 <b>Hour :</b> 12:58 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	