

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	125412 KM
File nr. :	1447880	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DWC479 / VF1JZ140647793549 /		yr of constructionr :	/
E-File nr. :		First registration :	14/09/2012
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / SCENIC	Fuel type :	DIESEL
Object nr. :	12144	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SYRAL BELGIUM NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	SCENIC Energ.Dynamique 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Interior

[x] SEAT FL OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

Number	Code	Description	Unit price	Depr.	Total
[x]		REAR BUMPER /LEFT/CORNER			
		DENT			
6	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]		REAR BUMPER/RIGHT/CORNER			
		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI		Depr.	Total
6	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]		REAR WINDOW/LEFT			
		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI		Depr.	Total
7	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI		Depr.	Total
7	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]		REAR MUDGUARD/RIGHT/FRONT			
		SCRATCH WITH PAINT DAMAGE		+DEUKEN	
		Repair paint - LI		Depr.	Total
8	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]		REAR DOOR/LEFT/CENTER			
		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI		Depr.	Total
5	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]		REAR DOOR/RIGHT/CENTER			
		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI		Depr.	Total
10	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]		REAR THRESHOLD/RIGHT/REAR			
		DENT			
		Repair paint - LI		Depr.	Total
9	0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR

[x]	WINDSCREEN/CENTER/LEFT		HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
4	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	BONNET/CENTER/LEFT		OTHER DAMAGES	CHEM. INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	FRONT MUDGUARD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		
	Number Code	Description	Unit price	Depr.	Total
0	0				
[x]	FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Interior

[x]	SEAT FR		DIRTY		
	Number Code	Description	Unit price	Depr.	Total
10	I 1 speciefiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		14.58 EUR

Others

RIM FRONT LEFT

	Number Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

	Number Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR

Number	Code	Description	Unit price	Depr.	Total
7	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
380.00	211.80	290.08	487.20	318.35	322.44	370.00	308.20	310.50	871.46
380.00	105.90	145.04	243.60	159.18	216.54	185.00	154.10	155.25	443.02

INNOVATIVE	TRADITIONAL	GENERAL	
505.22	3364.81	0	3870.03
HOG: 0	BG: 0		NA Deprec. 2187.62
			0.00%
			TOTAL 2187.62

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 09:38 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	