

D11G7L

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	74398 KM
File nr. :	1449997	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EBC956 / SB1KS56E30E072918 /		yr of constructionr :	/
E-File nr. :		First registration :	09/10/2012
VFS-nr. :		Color :	GREY
Make + Model :	TOYOTA / AURIS	Fuel type :	HYBRID
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	GEGIMMO SA	Co2:	93g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	AURIS HSD Premium 100PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1798
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	99	kW:	73
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	45	R	17	W
Rear tyre	215	45	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT DOOR/RIGHT/REAR DENT
- [x] FRONT DOOR/RIGHT/Front SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	HOLE/CRACK/TORN	+KRASSEN			
		Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	REAR MUDGUARD/LEFT/Front	SCRATCH WITH PAINT DAMAGE	+DEUK			
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	REAR MUDGUARD/RIGHT/Front	SCRATCH WITH PAINT DAMAGE	+DEUK			
		Repair paint - LI	New paint - E	Depr.	Total	
6	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	REAR DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	+DEUK			
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR	
[x]	REAR DOOR/LEFT/Front	DENT				
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	+DEUK			
		Repair paint - LI	New paint - E	Depr.	Total	
7	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR	
[x]	REAR DOOR/RIGHT/CENTER	DENT				
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	REAR DOOR/RIGHT/Front	DENT				
	Number	Code	Description	Unit price	Depr.	Total
0	0					

[x]	FRONT DOOR/LEFT/REAR		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x]	FRONT BUMPER/LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x]	FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE		
	Number	Code	Description	Unit price	Depr.
0	0				

Others

TYRE FRONT LEFT

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR			50 %	24.00 EUR

TYRE REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR			50 %	24.00 EUR

RIM FRONT LEFT

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	
		Repair paint - LI	New paint - E	Depr.	Total
2	5 LU =24.00 EUR			50 %	24.00 EUR

RIM REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	
		Repair paint - LI	New paint - E	Depr.	Total
2	5 LU =24.00 EUR			50 %	24.00 EUR

RIM FRONT RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	
	Repair paint - LI	New paint - E	Depr.	Total
2 5 LU =24.00 EUR			50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	TYRE	108.00 EUR	50 %	108.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	TYRE	108.00 EUR	50 %	108.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	ALLOY WHEEL	211.20 EUR	50 %	211.20 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	ALLOY WHEEL	211.20 EUR	50 %	211.20 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	ALLOY WHEEL	211.20 EUR	50 %	211.20 EUR

1	2	3	4	5	6	7	8	9	10
264.00	705.60	211.80	944.90	211.80	308.20	318.35	0	0	0
132.00	352.80	105.90	472.45	105.90	154.10	159.18	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	2964.65	0	2964.65
HOG: 0	BG: 0		NA Deprec. 1482.32
			0.00%
			TOTAL 1482.32

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/10/2017 Hour : 11:42 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	