

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	85643 KM
File nr. :	1448056	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DPG721 / VSSZZZ6JZDR063800 /		yr of constructionr :	/
E-File nr. :		First registration :	12/07/2012
VFS-nr. :		Color :	GREY
Make + Model :	SEAT / IBIZA	Fuel type :	DIESEL
Object nr. :	47822	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	VEOLIA SA/NV	Co2:	109g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	IBIZA ST Style 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RL : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel FR : [x] CONTINENTAL Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RR : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	185	60	R	15	H
Rear tyre	185	60	R	15	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/FRONT	DENT
[x]	FRONT DOOR/LEFT/CENTER	DENT
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	DENT												
<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>3</td> <td>15 LU =72.00 EUR</td> <td>0 EUR</td> <td>188.64 EUR</td> <td>50 %</td> <td>260.64 EUR</td> </tr> </tbody> </table>				Repair paint - LI	New paint - E	Depr.	Total	3	15 LU =72.00 EUR	0 EUR	188.64 EUR	50 %	260.64 EUR	
	Repair paint - LI	New paint - E	Depr.	Total										
3	15 LU =72.00 EUR	0 EUR	188.64 EUR	50 %	260.64 EUR									
[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	ROEST											
<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>0 LU =0.00 EUR</td> <td>246.56 EUR</td> <td>50 %</td> <td>246.56 EUR</td> </tr> </tbody> </table>				Repair paint - LI	New paint - E	Depr.	Total	4	0 LU =0.00 EUR	246.56 EUR	50 %	246.56 EUR		
	Repair paint - LI	New paint - E	Depr.	Total										
4	0 LU =0.00 EUR	246.56 EUR	50 %	246.56 EUR										
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE												
<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>0 LU =0.00 EUR</td> <td>254.68 EUR</td> <td>50 %</td> <td>254.68 EUR</td> </tr> </tbody> </table>				Repair paint - LI	New paint - E	Depr.	Total	4	0 LU =0.00 EUR	254.68 EUR	50 %	254.68 EUR		
	Repair paint - LI	New paint - E	Depr.	Total										
4	0 LU =0.00 EUR	254.68 EUR	50 %	254.68 EUR										
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE												
<table border="1"> <thead> <tr> <th>Number</th> <th>Code</th> <th>Description</th> <th>Unit price</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>6</td> <td>I 1 i-vab-herstr-01</td> <td>WINDOW REPAIR</td> <td>58.80 EUR</td> <td></td> <td>58.80 EUR</td> </tr> </tbody> </table>			Number	Code	Description	Unit price	Depr.	Total	6	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
Number	Code	Description	Unit price	Depr.	Total									
6	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR									
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE												
<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>5 LU =24.00 EUR</td> <td>169.44 EUR</td> <td>50 %</td> <td>193.44 EUR</td> </tr> </tbody> </table>				Repair paint - LI	New paint - E	Depr.	Total	2	5 LU =24.00 EUR	169.44 EUR	50 %	193.44 EUR		
	Repair paint - LI	New paint - E	Depr.	Total										
2	5 LU =24.00 EUR	169.44 EUR	50 %	193.44 EUR										

Interior

[x]	SEAT FL	CUT / TORN										
<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>25 LU =120.00 EUR</td> <td>0 EUR</td> <td>50 %</td> <td>120.00 EUR</td> </tr> </tbody> </table>				Repair paint - LI	New paint - E	Depr.	Total	1	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR
	Repair paint - LI	New paint - E	Depr.	Total								
1	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR								

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 3	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	43.74 EUR

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SEAT UPHOLSTERY TISSUE	96.00 EUR	50 %	96.00 EUR
3	1	REAR BUMPER	274.56 EUR	50 %	274.56 EUR
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
259.74	193.44	535.20	501.24	96.00	58.80	0	0	0	0
151.74	96.72	267.60	250.62	48.00	58.80	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
102.54	1541.88	0	1644.42
HOG: 0	BG: 1		NA Deprec. 873.48
			0.00%
			TOTAL 873.48

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 15:00 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	