

www.vabfleetservices.be Date: 17/10/2017 1/4

CYU41T

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	63191 KM
File nr. :	1447876	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LHB404 / WVWZZZAUZFW	7313470 /	yr of constructionr :	/
E-File nr. :		First registration :	28/09/2015
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	59063	Fuel:	
Classification:	E	Environment Class:	EURO 5
Customer company:	VAB RIJSCHOOL NV	Co2:	98g/km
Driver :		Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

Variant car:		Engine size:	1598		
Gear box :	Manueel	Number of places:	5		
Number of gears:	5	Number of doors:	5		
HP:	90	kW:	66		
Fisc HP		Imported vehicle:			
Animals transported:		Smoked in vehicle:			
Due date vehicle inspection:		Extra set of tires:	Extra set of tires:		
		Use:	Unknown		
General condition:					

Metallic paint:

Yes



www.vabfleetservices.be Date: 17/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :			Transport licence :		
Γax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

	[x] Width		1	Height			Туре	Rim	Index	7 I		
Wheel RES:	[x]	CONTINENTAL	Tyre:		OK		/	Rim:		/ Hubcap :		
Wheel RR:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/ Hubcap:		
Wheel FR:	[x]	CONTINENTAL	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/ Hubcap:	[x] SCRATCHED	
Wheel RL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/ Hubcap:		
Wheel FL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/ Hubcap:		

[x]	Width	Height	Туре	Rim	Index
Front tyre	195	65	R	15	Н
Rear tyre	195	65	R	15	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 17/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/SIDE/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT DOOR/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

	1	2	3	4	5	6	7	8	9	10
	0	0	0	0	0	0	0	0	0	0
ĺ	0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 0		NA Deprec.	0
			0.00%	
			TOTAL	0



www.vabfleetservices.be Date: 17/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time :	0 min	Waiting time : Reason :	0 min		Towing time : Reason :	0 min
NOT EXECUTED:	No					
Reason :						
Remark:						
Prices in EUR with	nout VAT					
Authorized by customer :				Executed by VAB Fleet Se	rvices	
Remark authorized cus	tomer :					
Date :	17/10/2017	Hour:				
Company :						
Executed by VAB Fleet Services						
E-Mail :	@					
Signature authorized by	customer					
×						