

www.vabfleetservices.be Date: 17/10/2017 1/4

CWF941

[X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	90660 KM
File nr. :	1446037	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FWB901 / YV1BW8481E129	95324 /	yr of constructionr :	/
E-File nr. :		First registration :	14/11/2013
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / V70	Fuel type :	DIESEL
Object nr. :	6276	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company:	SIEMENS NV	Co2:	109g/km
Driver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V70 D2 Kinetic 115PK	Country registration :	BELGIUM

Variant car:	BREAK	Engine size:	1560	
Gear box :	Manueel	Number of places:	5	
Number of gears:	6	Number of doors:	5	
HP:	114	kW:	84	
Fisc HP		Imported vehicle:		
Animals transported:		Smoked in vehicle:		
Due date vehicle inspection:		Extra set of tires:		
		Use:	Unknown	
General condition:				

Metallic paint:



www.vabfleetservices.be Date: 17/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]	
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK		
Cert. of reg. copy / Part 2:			Insurance certificate :			
Warning vest :	OK	[x]	Transport licence :			
Tax certificate :			Navigation CD/SD/DVD			
Fuel card :			Car radio :			
Mobile phone kit :			Extinguisher :	OK	[x]	
			Warning triangle :	OK	[x]	
First aid kit :	OK	[x]	Oil level :	OK	[x]	
Jack, wheelspanner :			Filled up :	0		

### Wheels and tyres: Summer tires

Wheel FL:	[x]	UNI	ROYAL	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap :	
Wheel RL:	[x]	MIC	HELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	
Wheel FR:	[x]	UNI	ROYAL	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	
Wheel RR:	[x]	MIC	HELIN	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel RES:	[x]			Tyre:		OK		/	Rim:				/ Hubcap:	
							ì							
		[x]		Width			Н	eight			Type		Rim	Index
Fron	<b>Front tyre</b> 225 50			R 17		W								
Rear	<b>Rear tyre</b> 225 50			R		17	W							

## Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:

Remark:



www.vabfleetservices.be Date: 17/10/2017 3/4

#### Conclusion

### Bodywork \& windows

[x] FRONT DOOR/LEFT/REAR

SCRATCH WITH PAINT DAMAGE

### STATUS: ACCEPTABLE / USAGE DAMAGE

#### Bodywork \& windows

[X] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR MUDGUARD/LEFT/FRONT DENT

[x] REAR DOOR/RIGHT/FRONT DENT

[x] FRONT BUMPER/CENTER/LEFT CHIPS

### STATUS: NOT ACCEPTABLE

#### **Others**

RIM REAR LEFT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
0	95.00	0	0	0	0	0	0	0	0
0	95.00	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
95.00		0	0	95.00
95.00	NA Deprec.		BG: 2	HOG: 0
'	0.00%			
95.00	TOTAL			



Date: 17/10/2017 www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES			UNDER CONDITION - DUSTY VEHICLE					
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No	<b>.</b>						
Remark :								
Prices in EUR w	ithout VAT							
Authorized by customer :			Executed by VAB Fleet Se	ervices				
Remark authorized o	customer :							
Date :	17/10/2017	<b>Hour:</b> 09:36						
Company :								
Executed by VAB Flo Services	eet							
E-Mail :	@							
Signature authorized b	by customer							