

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	55674 KM
File nr. :	1445019	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPM491 / WVWZZZ6RZEY052990 /		yr of constructionr :	/
E-File nr. :		First registration :	16/09/2013
VFS-nr. :		Color :	WHITE
Make + Model :	VOLKSWAGEN / POLO	Fuel type :	DIESEL
Object nr. :	37358	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Groupe Open Belgium SA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	POLO Trendline DPF 75PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:		Engine size:	1199
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	3
HP:	75	kW:	55
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		
Wheel RES:	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	175	70	R	14	T
Rear tyre	175	70	R	14	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] WINDSCREEN/CENTER/LEFT CHIPS
- [x] BONNET/CENTER/LEFT/FRONT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

	Repair paint - LI	New paint - E	Depr.	Total
[x] REAR DOOR/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE	BIJGESCHILDERD	
2 0 LU =0.00 EUR	241.34 EUR		50 %	241.34 EUR
[x] FRONT THRESHOLD/RIGHT/FRONT		DENT		
1 0 LU =0.00 EUR	248.40 EUR		50 %	248.40 EUR

1	2	3	4	5	6	7	8	9	10
248.40	241.34	0	0	0	0	0	0	0	0
124.20	120.67	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	489.74	0	489.74
HOG: 0	BG: 1		NA Deprec. 244.87
			0.00%
			TOTAL 244.87

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 09:53 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	