

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	120795 KM
File nr. :	1448098	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FEN720 / WVWZZZAUZDP081881 /		yr of constructionr :	2013 / 06
E-File nr. :		First registration :	07/06/2013
VFS-nr. :		Color :	
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	GOLF BER Trendline 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] MISSING/INCOMPLETE
Wheel RL : [x] CONTINENTAL Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] MISSING/INCOMPLETE
Wheel FR : [x] CONTINENTAL Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] MISSING/INCOMPLETE
Wheel RR : [x] CONTINENTAL Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] MISSING/INCOMPLETE
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE		
0	0			
[x]	REAR DOOR/CENTER/LEFT	DENT		
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR
[x]	REAR MUDGUARD/LEFT/REAR	DENT	3X+KRASSEN MET LAKSCHADES	
3	0 LU =0.00 EUR	308.20 EUR	50 %	308.20 EUR
[x]	REAR MUDGUARD/RIGHT/REAR	DENT		
6	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR
6	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR	19.80 EUR
[x]	FRONT DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)		
0	0			

[x]	ROOF /FRONT/LEFT/CENTER		DENT		3X		
	Number	Code	Description	Unit price	Depr.	Total	
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR	
	Number	Code	Description	Unit price	Depr.	Total	
4	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR	
[x]	FRONT BUMPER/CENTER/RIGHT		DENT				
	Number	Code	Description	Unit price	Depr.	Total	
7	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR	

Interior

[x]	CENTER CONSOLE		OTHER DAMAGES				
			Repair paint - LI	New paint - E	Depr.	Total	
1	0 LU	=0.00 EUR	0 EUR		50 %		
[x]	FLOOR FL		HOLE				
	Number	Code	Description	Unit price	Depr.	Total	
1	I 1	i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR		43.92 EUR	
	Number	Code	Description	Unit price	Depr.	Total	
1	I 1	i-vab-inttap-02	SUPPL REPAIR CARPET	18.00 EUR		18.00 EUR	
[x]	ROOF UPHOLSTERY		BURNT				
	Number	Code	Description	Unit price	Depr.	Total	
7	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR	

Others

	HUB CAP FL						
			Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU	=0.00 EUR			50 %		
	HUB CAP REAR L						
			Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU	=0.00 EUR			50 %		
	HUB CAP REAR RIGHT						
			Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU	=0.00 EUR			50 %		

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	VERLUCHTINGSROOSTER	60.00 EUR	50 %	60.00 EUR
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
121.92	63.00	308.20	82.80	120.00	82.80	130.14	0	0	0
91.92	63.00	154.10	82.80	60.00	82.80	130.14	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
420.66	488.20	0	908.86
HOG: 0	BG: 0		NA Deprec. 664.76
			0.00%
			TOTAL 664.76

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/10/2017 Hour : 10:30 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	