

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

|                                     |                         |                                 |                               |
|-------------------------------------|-------------------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING         | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: DIRTY [x] |
| <b>Owner :</b>                      |                         | <b>Mileage :</b>                | 93003 KM                      |
| <b>File nr. :</b>                   | 1450406                 | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                         | <b>Mileag ref. service :</b>    | 0                             |
| 1FKJ760 / WWZZZ6RZEY038874 /        |                         | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                         | <b>First registration :</b>     | 26/07/2013                    |
| <b>VFS-nr. :</b>                    |                         | <b>Color :</b>                  | BLACK                         |
| <b>Make + Model :</b>               | VOLKSWAGEN / POLO       | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 | 713108                  | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             |                         | <b>Environment Class:</b>       | EURO 5                        |
| <b>Customer company :</b>           | HANDSON & PARTNERS NV   | <b>Co2:</b>                     | 99g/km                        |
| <b>Driver :</b>                     |                         | <b>Remote controls:</b>         | 2                             |
| <b>Covering :</b>                   | TISSUE                  | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle kind :</b>               | VEHICLE                 | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               | POLO Trendline DPF 75PK | <b>Country registration :</b>   | BELGIUM                       |

|                                     |         |                            |         |
|-------------------------------------|---------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   | No      | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 |         | <b>Engine size:</b>        | 1199    |
| <b>Gear box :</b>                   | Manueel | <b>Number of places:</b>   | 5       |
| <b>Number of gears:</b>             | 5       | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 75      | <b>kW:</b>                 | 55      |
| <b>Fisc HP</b>                      |         | <b>Imported vehicle:</b>   |         |
| <b>Animals transported:</b>         | No      | <b>Smoked in vehicle:</b>  | No      |
| <b>Due date vehicle inspection:</b> |         | <b>Extra set of tires:</b> | No      |
|                                     |         | <b>Use:</b>                | Unknown |
| <b>General condition:</b>           |         |                            |         |

|                                 |                          |
|---------------------------------|--------------------------|
| Original registr. number : OK   | Service manual : OK      |
| Cert. of reg. / Part 1:         | Cert. of conformity : OK |
| Cert. of reg. copy / Part 2: OK | Insurance certificate :  |
| Warning vest :                  | Transport licence :      |
| Tax certificate :               | Navigation CD/SD/DVD     |
| Fuel card :                     | Car radio : OK           |
| Mobile phone kit :              | Extinguisher : OK        |
| First aid kit : OK              | Warning triangle : OK    |
| Jack, wheelspanner : OK         | Oil level : OK           |
|                                 | Filled up : 0            |

## Wheels and tyres: Summer tires

|            |             |        |    |          |       |   |          |               |
|------------|-------------|--------|----|----------|-------|---|----------|---------------|
| Wheel FL:  | BRIDGESTONE | Tyre : | OK | 2-4/     | Rim : | / | Hubcap : |               |
| Wheel RL : | BRIDGESTONE | Tyre : | OK | [x] 2-4/ | Rim : | / | Hubcap : |               |
| Wheel FR : | BRIDGESTONE | Tyre : | OK | 2-4/     | Rim : | / | Hubcap : | SCRATCHED     |
| Wheel RR : | BRIDGESTONE | Tyre : | OK | [x] 2-4/ | Rim : | / | Hubcap : | [x] SCRATCHED |
| Wheel RES: | BRIDGESTONE | Tyre : | OK | /        | Rim : | / | Hubcap : |               |

|            | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 175   | 70     | R    | 14  | T     |
| Rear tyre  | 175   | 70     | R    | 14  | T     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |   |          |  |
|------------|--|--------|----|---|-------|---|----------|--|
| Wheel FL:  |  | Tyre : | OK | / | Rim : | / | Hubcap : |  |
| Wheel RL : |  | Tyre : | OK | / | Rim : | / | Hubcap : |  |
| Wheel FR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |  |
| Wheel RR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |  |
| Wheel RES: |  | Tyre : | OK | / | Rim : | / | Hubcap : |  |

|            | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

|     |                       |                                |
|-----|-----------------------|--------------------------------|
| [x] | REAR BUMPER/LEFT/LEFT | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | REAR DOOR/LEFT/CENTER | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | FRONT DOOR/LEFT/REAR  | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | FRONT BUMPER/LEFT     | SCRATCH WITH PAINT DAMAGE      |

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                           |                           |                          |                      |              |              |
|-----|---------------------------|---------------------------|--------------------------|----------------------|--------------|--------------|
| [x] | REAR MUDGUARD/RIGHT/FRONT | SCRATCH WITH PAINT DAMAGE |                          |                      |              |              |
|     |                           |                           | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 2   | 0 LU =0.00 EUR            | 246.56 EUR                |                          |                      | 50 %         | 246.56 EUR   |

### Interior

|               |                     |   |                   |              |              |  |
|---------------|---------------------|---|-------------------|--------------|--------------|--|
| SEAT FR       |                     | HOLE  |                   |              |              |  |
| <b>Number</b> | <b>Code</b>         | <b>Description</b>                          | <b>Unit price</b> | <b>Depr.</b> | <b>Total</b> |  |
| 1             | I 1 i-vab-intvtr-01 | VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER) | 64.32 EUR         |              | 64.32 EUR    |  |

### Others

|                    |                |  |                          |                      |              |              |
|--------------------|----------------|--|--------------------------|----------------------|--------------|--------------|
| HUB CAP REAR RIGHT |                |  |                          |                      |              |              |
|                    |                |  | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 3                  | 0 LU =0.00 EUR |  |                          |                      | 50 %         |              |

|            |                |  |                          |                      |              |              |
|------------|----------------|--|--------------------------|----------------------|--------------|--------------|
| HUB CAP FR |                |  |                          |                      |              |              |
|            |                |  | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 3          | 0 LU =0.00 EUR |  |                          |                      | 50 %         |              |

### Pieces

|               |             |                    |                   |              |              |
|---------------|-------------|--------------------|-------------------|--------------|--------------|
| <b>Number</b> | <b>Code</b> | <b>Description</b> | <b>Unit price</b> | <b>Depr.</b> | <b>Total</b> |
| 3             | 1           | WHEEL CAP          | 24.00 EUR         | 50 %         | 24.00 EUR    |
| <b>Number</b> | <b>Code</b> | <b>Description</b> | <b>Unit price</b> | <b>Depr.</b> | <b>Total</b> |
| 3             | 1           | WHEEL CAP          | 24.00 EUR         | 50 %         | 24.00 EUR    |

|          |          |          |          |          |          |          |          |          |           |
|----------|----------|----------|----------|----------|----------|----------|----------|----------|-----------|
| <b>1</b> | <b>2</b> | <b>3</b> | <b>4</b> | <b>5</b> | <b>6</b> | <b>7</b> | <b>8</b> | <b>9</b> | <b>10</b> |
| 64.32    | 246.56   | 48.00    | 0        | 0        | 0        | 0        | 0        | 0        | 0         |
| 64.32    | 123.28   | 24.00    | 0        | 0        | 0        | 0        | 0        | 0        | 0         |

| INNOVATIVE | TRADITIONAL | GENERAL |                     |
|------------|-------------|---------|---------------------|
| 64.32      | 294.56      | 0       | <b>358.88</b>       |
| HOG: 0     | BG: 1       |         | NA Deprec. 211.60   |
|            |             |         | 0.00%               |
|            |             |         | <b>TOTAL 211.60</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

|                           |  |   |
|---------------------------|--|---|
| <b>Extra Time :</b> 0 min | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No  |  |   |
| <b>Reason :</b>           |  |   |
| <b>Remark :</b>           |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 19/10/2017 <b>Hour :</b> 16:28<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br><br>   |                                |