

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	177828 KM
File nr. :	1451049	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1BPD058 / WAUZZZ4G5CN022105 /		yr of constructionr :	/
E-File nr. :		First registration :	25/07/2011
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A6	Fuel type :	DIESEL
Object nr. :	6437	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ARCO INFORMATION NV	Co2:	129g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A6 BER 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	FULDA	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	FULDA	Tyre :	OK	[x]	0-1.6/	Rim :	/	Hubcap :
Wheel FR :	[x]	FULDA	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	FULDA	Tyre :	OK	[x]	0-1.6/	Rim :	[x]	WHEEL SCRATCHED
Wheel RES:	[x]	FULDA	Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	16	V
Rear tyre	225	60	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE
- [x] BONNET/CENTER/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT BUMPER/CENTER/LEFT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

		Repair paint - LI	New paint - E	Depr.	Total
[x]	REAR BUMPER/RIGHT/RIGHT				SCRATCH WITH PAINT DAMAGE
2	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER				DENT
Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Interior

[x]	SEAT FL				STAIN
Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR
[x]	SEAT FR				STAIN
Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

1	2	3	4	5	6	7	8	9	10
29.16	254.16	63.00	0	0	0	0	0	0	0
29.16	127.08	63.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
92.16	254.16	0	346.32
HOG: 0	BG: 2		NA Deprec. 219.24
			0.00%
			TOTAL 219.24

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 24/10/2017 Hour : 16:22 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	