

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	182499 KM
File nr. :	1449587	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1SFB341 / WMWZD11050WL27391 /		yr of constructionr :	/
E-File nr. :		First registration :	05/10/2012
VFS-nr. :		Color :	BLACK
Make + Model :	MINI / COUNTRYMAN	Fuel type :	DIESEL
Object nr. :	75189	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	DIFFERENT HOTELS	Co2:	115g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate :
Warning vest : OK	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	CONTINENTAL	Tyre :	OK	1.6-2/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	CONTINENTAL	Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :	CONTINENTAL	Tyre :	OK	1.6-2/	Rim :		/	Hubcap :
Wheel RR :	CONTINENTAL	Tyre :	OK	/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

Interior

[x] DOOR IN FL CARVED

[x] DOOR IN FR CARVED

[x] DOOR IN REAR L CARVED

[x] DOOR IN REAR RIGHT CARVED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE MEERDERE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR

Interior

[x] LUGGAGE COVER MISSING/INCOMPLETE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	0 EUR		50 %	

Accessories and others

[x] SIDE PROTECTION MISSING/INCOMPLETE

	Repair paint - LI	New paint - E	Depr.	Total
3 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	CORD BACK SHELF	21.60 EUR	50 %	21.60 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	SIERLIJST	45.00 EUR	50 %	45.00 EUR

1	2	3	4	5	6	7	8	9	10
21.60	169.44	69.00	0	0	0	0	0	0	0
10.80	84.72	34.50	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	260.04	0	260.04
HOG: 0	BG: 1		NA Deprec. 130.02
			0.00%
			TOTAL 130.02

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/10/2017 Hour : 11:47 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	