

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	131597 KM
File nr. :	1445900	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FJN698 / WBAFW11020D270351 /		yr of constructionr :	/
E-File nr. :		First registration :	17/07/2013
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 5	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	123g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	5 BER 520dA Start/Stop 163PK aut	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	4
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	GOODYEAR	Tyre :	OK	4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :
Wheel RL :	GOODYEAR	Tyre :	OK	4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :
Wheel FR :	GOODYEAR	Tyre :	OK	4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :
Wheel RR :	GOODYEAR	Tyre :	OK	4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/ Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	V
Rear tyre	225	55	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/ Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/ Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/ Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/ Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/ Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	WINDSCREEN/CENTER/LEFT	CHIPS
[x]	FRONT DOOR/RIGHT/CENTER	DENT
[x]	BONNET/CENTER/RIGHT	DENT
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	MEERDERE		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE			
			Unit price	Depr.	Total
1	I1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

1	2	3	4	5	6	7	8	9	10
115.56	254.16	0	0	0	0	0	0	0	0
115.56	127.08	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	254.16	0	369.72
HOG: 0	BG: 2		NA Deprec. 242.64
			0.00%
			TOTAL 242.64

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 13:42 Company : Executed by VAB Fleet Services E-Mail :	Executed by VAB Fleet Services
Signature authorized by customer 	