

www.vabfleetservices.be Date: 23/10/2017 1/4

CXS2S6

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Vehicle type :

308 SW Access 92PK

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 167985 KM File nr. : Mileage start / arrival: 0 / 01447101 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FTE419 / VF34E9HP0DS191773 / E-File nr. : First registration: 17/10/2013 Color: VFS-nr.: **GREY** Make + Model : Fuel type : PEUGEOT / 308 **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: WURTH BELUX NV 119g/km Driver : Remote controls: 1 TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0

Country registration:

BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	92	kW:	68
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:		1	



www.vabfleetservices.be Date: 23/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :			Transport licence :		
Γax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

1 1 2 2 3 2 2 3	-3 - 0											
Front	tvre		195				65		R		15	Н
		[x]	Width			Н	eight		Type		Rim	Index
Wheel RES:	[x]		Tyre:		OK		/	Rim:		/	Hubcap :	
			-				,				•	
Wheel RR:	[x]	FIRESTONE	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	FIRESTONE	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RL:	[x]	FIRESTONE	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FL:	[x]	FIRESTONE	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap: [x	SCRATCHED

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
_					

[x	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 23/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

[x] BONNET/CENTER/RIGHT CHIPS

Interior

[x] DOOR IN FL SCRATCHED

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
0	0	0	0
NA Deprec. 0		BG: 0	HOG: 0
0.00%			
TOTAL			



23/10/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No					
CIRCUMST	FANCES		NORMAL CONCLU	SION	
Extra Time :	0 min	Waiting time: 0 min Reason:	n	Towing time : Reason :	0 min
NOT EXECUTED : Reason :	No	I		l	
Remark:					
Prices in EUR w	ithout VAT				
Authorized by customer :			Executed by VAB Fleet Se	rvices	
Remark authorized o	customer :				
Date :	23/10/2017	Hour: 09:15			
Company : Executed by VAB Flo	eet				
Services E-Mail :	@				
Signature authorized b	by customer				