

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	113753 KM
File nr. :	1451588	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FRF554 / YV1MV8481E2105016 /		yr of constructionr :	/
E-File nr. :		First registration :	01/10/2013
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / V40	Fuel type :	DIESEL
Object nr. :	51411	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CEGEKA NV	Co2:	88g/km
Driver :		Remote controls:	2
Covering :	TISSUE-ALCANTARA	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V40 D2 Base 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	[x]	Insurance certificate :	[x]
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	MICHELIN	Tyre :	OK		2-4/	Rim :	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	MICHELIN	Tyre :	OK		2-4/	Rim :	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	Tyre :	OK		/	Rim :		/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT
[x]	REAR BUMPER/SIDE/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	WINDSCREEN/RIGHT	CHIPS
[x]	FRONT BUMPER/RIGHT	CHIPS

Accessories and others

VEH COVERED WITH STICKERS	CHIPS
OUTSIDE MIRROR LEFTHAND SIDE	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		308.20 EUR		50 %	308.20 EUR
[x]	WINDSCREEN/LEFT	HOLE/CRACK/TORN			HERSTELD	
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	BONNET/CENTER/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		290.08 EUR		50 %	290.08 EUR

Others

		RIM REAR RIGHT				
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
308.20	95.00	290.08	0	0	0	0	0	0	0
154.10	95.00	145.04	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	598.28	0	693.28
HOG: 0	BG: 0		NA Deprec. 394.14
			0.00%
			TOTAL 394.14

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/10/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	