

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	149250 KM
File nr. :	1453594	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EJX359 / WAUZZZ8UXDR053165 /		yr of constructionr :	/
E-File nr. :		First registration :	02/01/2013
VFS-nr. :		Color :	WHITE
Make + Model :	AUDI / Q3	Fuel type :	DIESEL
Object nr. :	703585	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BAXALTA SERVICES EUROPE	Co2:	137g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	>6/	Rim :	/
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]	GOODYEAR	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	65	R	16	M+S
Rear tyre	215	65	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

Interior

[x] SEAT REAR L OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] WINDSCREEN/LEFT WINDOW DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR

[x] FRONT/RIGHT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
4 10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

[x] FRONT BUMPER/RIGHT/CORNER DENT

	Repair paint - LI	New paint - E	Depr.	Total
3 15 LU =72.00 EUR	211.80 EUR		50 %	283.80 EUR

Interior

[x] FLOOR BOOT STAIN

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1 BUMPER GRID		30.00 EUR	50 %	30.00 EUR

Number	Code	Description	Unit price	Depr.	Total
4	1 FRONT		150.00 EUR	50 %	150.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	58.80	313.80	198.00	0	0	0	0	0	0
14.58	58.80	156.90	99.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
73.38	511.80	0	585.18
HOG: 0	BG: 0		NA Deprec. 329.28
			0.00%
			TOTAL 329.28

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 30/10/2017 Hour : 13:20 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	